


UNIVERSITYS PENNSYLVANIA LIBRARIES





Soluble Salts in Porous Materials: Evaluating Effectiveness of their Removal

Joshua Freedland

A THESIS

In

Historic Preservation

Presented to the Faculties of the University of Pennsylvania in Partial Fulfillment of the Requirements for the Degree of

MASTER OF SCIENCE

1999

Dr. A. Elena Charola

Lecturer, Historic Preservation

Advisor

Dr. Sylvia Centeno

Metropolitan Museum of Art

Reader

David G. De Long

Professor of Architecture

- MICGOLET

Graduate Group Chair

F it NA 224/

OF FENNSYLVANIA LIBRARIES

TABLE OF CONTENTS

LIST OF TABLES	iv
LIST OF GRAPHS	vi
LIST OF ILLUSTRATIONS	ix
1. INTRODUCTION	1
2. DECAY MECHANISMS DUE TO SALT CRYSTALLIZATION	4
2.1 MECHANISMS OF DECAY: MECHANICAL	4
2.2 MECHANISMS OF DECAY: OTHER	6
2.3 EFFECT ON CONSERVATION TREATMENTS	7
2.4 DAMAGE	8
2.5 ORIGINS OF SOLUBLE SALTS	9
3. CONSERVATION	14
3.1 IDENTIFICATION OF SALTS	14
3.2 IMMOBILIZATION OF SALTS	15
3.3 DESALINATION: BUILDINGS	17
3. 4 DESALINATION: ARCHAEOLOGICAL CERAMICS	21
4. CHARACTERIZATION OF TILES	26
5. ANALYTICAL TECHNIQUES	36
5.1 TITRATIONS	37
5.2 TEST TITRATIONS	40
5.3 CALIBRATION CURVES	52



54	TITRA	TION	PRAC	FDIRE

6. DESALINATION TESTS	59
6.1 Introduction	59
6.2 PROLONGED IMMERSION	59
6.3 REPEATED WASHINGS	63
6.4 REMOVAL OF SALT MIXTURES	70
6.5 POULTICE	74
6.6 PRESSURE POULTICE	76
7. CONCLUSION	
APPENDIX A: SOLUBILITY OF COMMON SALTS FOUND IN BUILDINGS	80
APPENDIX B: PORE MEASUREMENTS OF EARTHENWARE TILE	81
APPENDIX C: PORE MEASUREMENTS OF STONEWARE TILE	82
APPENDIX D: ADDITIONAL DESALINATION GRAPHS AND TABLES	83
BIBLIOGRAPHY	91
INDEX	108



LIST OF TABLES

TABLE 1: SALT CONCENTRATION IN SEA WATER	10
TABLE 2: POROSITY OF EARTHENWARE TILES	27
TABLE 3: POROSITY OF STONEWARE TILES	30
TABLE 4: EQUIVALENT ION CONDUCTANCE AT 25° C	30
TABLE 5: SOLUBILITY OF PRECIPITATES	4(
TABLE 6: TEST TITRATIONS OF SINGLE SALTS	42
TABLE 7: TEST TITRATIONS OF SODIUM CHLORIDE WITH SODIUM SULFATE	44
TABLE 8: TEST TITRATIONS OF SODIUM CHLORIDE WITH GYPSUM	45
TABLE 9: TEST TITRATIONS OF SODIUM SULFATE WITH SODIUM CHLORIDE	49
TABLE 10: TEST TITRATIONS OF GYPSUM WITH SODIUM CHLORIDE	51
TABLE 11: TEST TITRATIONS OF CONDUCTANCE ESTIMATED CONCENTRATIONS	58
TABLE 12: PERCENT OF SALTS BY PROLONGED IMMERSION IN 150 MILLILITERS OF WA	ATER 60
TABLE 13: PERCENT OF SALTS BY PROLONGED 1MMERSION IN 300 MILLILITERS OF WA	TER 63
TABLE 14: PERCENT OF SALT REMOVED DURING REPEATED WASHINGS WITH 150 MILLILITERS	63
TABLE 15: PERCENT OF SALT REMOVED DURING REPEATED WASHINGS WITH 300 MILLILITERS	64
TABLE 16: PERCENT OF SALT REMOVED DURING INTERMITTENT WASHINGS	66
TABLE 17: PERCENT OF SALT REMOVED DURING INTERMITTENT WASHINGS FROM EARTHENWARE TILES	70
TABLE 18: PERCENT OF SALT REMOVED DURING INTERMITTENT WASHINGS FROM STONEWARE TILES	71
TABLE 19: RATIO OF AMOUNTS OF SODIUM CHLORIDE TO SULFATE SALT REMOVED FI EARTHENWARE TILES	ROM 73
TABLE 20: RATIO OF SODIUM CHLORIDE TO SULFATE SALT REMOVED FROM STONEW. TILES	ARE 74



TABLE 21: PERCENT OF SALT REMOVED WITH POULTICE	75
TABLE 22: PERCENT OF SALT REMOVED WITH PRESSURE POULTICE	77
TABLE 23: RATIO OF SODIUM CHLORIDE TO SULFATE SALT REMOVED WITH PRESSURE POULTICE	77
TABLE D1: GRAMS OF SALT REMOVED DURING INTERMITTENT WASHINGS OF EARTHENWARE TILES	88
TABLE D2: GRAMS OF SALT REMOVED DURING INTERMITTENT WASHINGS OF STONEWA	
TILES	89
TARLE D3: CRAMS OF SALT REMOVED WITH PRESSURE POULTICE	on



LIST OF GRAPHS

GRAPH 1: DRYING RATE OF EARTHENWARE TILE	34
GRAPH 2: DRYING RATE OF STONEWARE TILES	34
GRAPH 3: TEST TITRATIONS OF SINGLE SALTS SODIUM CHLORIDE WITH SILVER NITH	RATE 41
GRAPH 4: TEST TITRATIONS OF SINGLE SALTS SODIUM SULFATE WITH BARIUM CHLO	ORIDE 41
GRAPH 5: TEST TITRATIONS OF SINGLE SALTS GYPSUM WITH BARIUM CHLORIDE	41
GRAPH 6: TEST TITRATIONS OF SODIUM CHLORIDE IN THE PRESENCE OF 0.00625M S SULFATE	SODIUM 43
GRAPH 7: TEST TITRATIONS OF SODIUM CHLORIDE IN THE PRESENCE OF 0.00125M S SULFATE	SODIUM 43
GRAPH 8: TEST TITRATIONS OF SODIUM CHLORIDE IN THE PRESENCE OF 0.00625M S SULFATE	Sodium 43
GRAPH 9: TEST TITRATIONS OF SODIUM CHLORIDE IN THE PRESENCE OF 0.000625M GYPSUM	46
GRAPH 10: TEST TITRATIONS OF SODIUM CHLORIDE IN THE PRESENCE OF 0.000125M GYPSUM	46
GRAPH 11: TEST TITRATIONS OF SODIUM CHLORIDE IN THE PRESENCE OF 0.0025M GYPSUM	46
GRAPH 12: TEST TITRATIONS OF SODIUM SULFATE IN THE PRESENCE OF 0.00625M S CHLORIDE	ODIUM 48
GRAPH 13: TEST TITRATIONS OF SODIUM SULFATE IN THE PRESENCE OF 0.00625M S CHLORIDE	ODIUM 48
GRAPH 14: TEST TITRATIONS OF SODIUM SULFATE IN THE PRESENCE OF 0.00125M S CHLORIDE	ODIUM 48
GRAPH 15: TEST TITRATIONS OF GYPSUM IN THE PRESENCE OF 0.025M SODIUM CHI	CORIDE 50
GRAPH 16: TEST TITRATIONS OF GYPSUM IN THE PRESENCE OF 0.005M SODIUM CHI	ORIDE 50
GRAPH 17: TEST TITRATIONS OF GYPSUM IN THE PRESENCE OF 0.025M SODIUM CHU	LORIDE 50



GRAPH 18: SODIUM CHLORIDE CONDUCTANCE (K) STANDARDIZATION CURVE	53
GRAPH 19: SODIUM SULFATE CONDUCTANCE (K) STANDARDIZATION CURVE	54
GRAPH 20: GYPSUM CONDUCTANCE (K) STANDARDIZATION CURVE	55
GRAPH 21: COMPARISON OF DESALINATION BY PROLONGED IMMERSION	62
GRAPH 22: COMPARISON OF DESALINATION BY PROLONGED IMMERSION	62
GRAPH 23: COMPARISON OF DESALINATION BY REPEATED WASHINGS	65
GRAPH 24: COMPARISON OF DESALINATION BY REPEATED WASHINGS	65
GRAPH 25: COMPARISON OF PERCENT OF SODIUM CHLORIDE REMOVED FROM EARTHENWARE TILES AFTER 3 HOURS IN WATER	67
GRAPH 26: COMPARISON OF PERCENT OF SODIUM CHLORIDE REMOVED FROM STONE TILES AFTER 3 HOURS IN WATER	EWARE 67
GRAPH 27: COMPARISON OF PERCENT OF SODIUM SULFATE REMOVED FROM EARTHENWARE TILES AFTER 6 HOURS IN WATER	68
GRAPH 28: COMPARISON OF PERCENT OF SODIUM SULFATE REMOVED FROM STONEY TILES AFTER 6 HOURS IN WATER	VARE 68
GRAPH 29: COMPARISON OF PERCENT OF GYPSUM REMOVED FROM EARTHENWARE TAFTER 6 HOURS IN WATER	TILES 69
GRAPH DI: GRAMS OF SODIUM CHLORIDE REMOVED DURING 150ML PROLONGED IMMERSION OF EARTHENWARE TILE	83
GRAPH D2: GRAMS OF SODIUM CHLORIDE REMOVED DURING 300ML PROLONGED IMMERSION OF EARTHENWARE TILE	83
GRAPH D3: GRAMS OF SODIUM CHLORIDE REMOVED DURING 150ML PROLONGED IMMERSION OF STONEWARE TILE	84
GRAPH D4: GRAMS OF SODIUM CHLORIDE REMOVED DURING 300ML PROLONGED IMMERSION OF STONEWARE TILE	84
GRAPH D5: GRAMS OF SODIUM SULFATE REMOVED DURING 150ML PROLONGED IMMERSION OF EARTHENWARE TILE	85
GRAPH D6: GRAMS OF SODIUM SULFATE REMOVED DURING 300ML PROLONGED IMMERSION OF EARTHENWARE TILE	85
GRAPH D7: GRAMS OF SODIUM SULFATE REMOVED DURING 150ML PROLONGED IMMERSION OF STONEWARE TILE	86



GRAPH D8: GRAMS OF SODIUM SULFATE REMOVED DURING 300ML PROLONGED IMMERSION OF STONEWARE TILE	86
GRAPH D9: GRAMS OF GYPSUM REMOVED DURING 150ML PROLONGED IMMERSION OF EARTHENWARE TILE	87
GRAPH D10: GRAMS OF GYPSUM REMOVED DURING 300ML PROLONGED IMMERSION OF EARTHENWARE TILE	87



LIST OF ILLUSTRATIONS

FIGURE 1: PHOTOMICROGRAPH OF EARTHENWARE TILE THIN SECTION IN TRANSMITTED LIGHT (MAGNIFICATION 25X).	28
FIGURE 2: PHOTOMICROGRAPH OF EARTHENWARE TILE THIN SECTION UNDER CROSS POLARIZED LIGHT (MAGNIFICATION 25X).	28
FIGURE 3: PHOTOMICROGRAPH OF EARTHENWARE TILE THIN SECTION IN TRANSMITTEE LIGHT (MAGNIFICATION 100X).) 29
FIGURE 4: PHOTOMICROGRAPH OF EARTHENWARE TILE THIN SECTION IN CROSSED POLARIZED LIGHT (MAGNIFICATION 100X).	29
FIGURE 5: PHOTOMICROGRAPH OF STONEWARE TILE THIN SECTION IN TRANSMITTED LIGHT (MAGNIFICATION 25X).	31
FIGURE 6: PHOTOMICROGRAPH OF STONEWARE TILE THIN SECTION UNDER CROSS POLARIZED LIGHT.	31
FIGURE 7: PHOTOMICROGRAPH OF STONEWARE TILE THIN SECTION UNDER TRANSMITTI LIGHT (MAGNIFICATION 100x).	ED 32
FIGURE 8: PHOTOMICROGRAPII OF STONEWARE TILE THIN SECTION UNDER CROSS POLARIZED LIGHT (MAGNIFICATION 100X).	32



1. Introduction

Soluble salts are generally considered to be the single most important deterioration factor for porous materials. Salt decay leads to both aesthetic damage, through the formation of efflorescences, and physical damage, through the disaggregation of the material. A significant body of literature exists which attempts to explain and quantify the results of soluble salt decay. However, the manner in which salts crystallize within the pores of a material is yet to be elucidated. Furthermore, no agreement exists on the mechanisms ruling this process. The complexity of the problem increases dramatically when combinations of different salts are present which is the case for building materials.

Although difficult and seldom complete, removal of the soluble salts is the most obvious conservation treatment for porous materials facing salt decay. While it is easy to quantify the amount of salts within a building sample, no good method exists for accurately quantifying the distribution and the total amount of soluble salts in an entire building. Lower regions of a wall will have different types and concentrations of salts than upper portions.¹ Similar differences can also be observed from the exterior wall surfaces to the interior of the walls.² So far only destructive techniques can be used to determine salt concentrations. Since the quantity and mix of salts throughout a building

¹ Andreas Arnold. "Rising Damp and Saline Minerals." in *Fourth International Congress on the Deterioration and Preservation of Stone Objects July 7-9, 1982 Proceedings*, ed. K. L. Gauir and J. A. Gwinn (Louisville: University of Louisville, 1982), p. 11-28

² Fernand Auger, "World Limestone Decay under Marine Spray and Conditions." in *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on*



concerns. As a result, the effectiveness of any salt removal method from an actual building or object can only be estimated, even if a large number of samples had originally been taken to quantify the salt content. Although many publications discuss the methodology and the amount of salt removed, not knowing the original amount present leaves open the question of the treatment's effectiveness.

This study focuses on the removal of soluble salts from two sets of ceramic tiles with different porosities containing known amounts of salts. The tiles had been impregnated with individual salts or their combinations. The individual salts were sodium chloride, sodium sulfate, or gypsum, and the combinations were mixtures of sodium chloride with either sodium sulfate or gypsum. These mixtures were chosen since they are the most frequently found in both masonry materials and archaeological ceramics. The salts had been introduced into the tiles by immersion in saturated solutions, and the amount of salts deposited in them determined gravimetrically.³

The study assesses the efficiency of salt removal by either immersion procedures or poultices. The tiles were totally immersed in different amounts of deionized water for different lengths of time or poulticed with absorbent clays. Absorbent clays in poultices is a common desalination technique for buildings, as well as, for especially fragile ceramic objects. Conductimetric measurements were used to monitor the amount of salts removed. Immersion procedures are most applicable to discrete removable objects, such as archaeological ceramics or removable architectural elements. The evaluation of the

Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989. ed. Fulvio Zezza (Brescia, Italy: Grafo, 1990), p. 65-69.



removed salts using the described desalination techniques contributes fundamental information regarding the effectiveness of these procedures for different salts and their mixtures. Since the total amount of salts in each tile was known, it was possible to evaluate the actual effectiveness of the removal procedure from a body of a given porosity. This information can also serve as a guideline to estimate the remaining salt content in a given object of similar porosity after desalination with one of these techniques.

³ A. Elena Charola and Sara Nunberg, "Soluble Salts in Ceramic Bodies: Deterioration Due to Minimal Changes in Relative Humidity," Manuscript to be submitted to *Studies in Conservation*,



2. DECAY MECHANISMS DUE TO SALT CRYSTALLIZATION

2.1 MECHANISMS OF DECAY: MECHANICAL

Despite numerous studies, no conclusive explanation of how salts damage porous materials exists.4 Much of the literature relies on the explanation that as a salt crystallizes it fills a pore. When there is no more space for a salt in a pore to crystallize, it exerts pressure on the pore walls. This deterioration mechanism is said to increase when a salt hydrates easily. The increase in volume resulting from the hydration of a salt creates pressure which damages the interior pore structure of the material. The earliest explanations state that for salts such as sodium sulfate or magnesium sulfate, which can exist in a hydrated form, cause damage: "due to the increase in volume, as they get a higher degree of hydration. This increase in volume produces cracking of the stones or their components." 5 While the 314% increase in size of sodium sulfate decahydrate is significant, attributing this as the cause of deterioration assumes "a solid state or insitu conversion of Na₂SO₄ to Na₂SO₄•10H₂O. It is difficult to imagine how orthorombic Na₂SO₄ can be converted to monoclinic Na₂SO₄•10H₂O by a solid state reaction."⁶

⁵ Andreas Arnold. "Soluble Salts and Stone Weathering." in *The Conservation of Stone 1 Proceedings of the International Symposium Bologna, June 19-21, 1975*, ed. by R. Rossi-Manaresi (Bologna: Centro Per La Conservazione Delle Sculture All'Aperto, 1976). p. 133.

⁴ Micahel Steiger and Anke Zennert. "Crystallization Properties of Salt Mixtures: Comparison of Experimental results and Model Calculations." in *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September – 4 October 1996*, ed. Joseph Riederer (Berlin: Moller Druck und Verlag, 1996). p. 535.

⁶ S. Chatterji, P. Christensen, and G. Overgaard, "Mechanisms of Breakdown of Natural Stones Caused by Sodium Salts," in *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-2 10 1979* (Padova: Universita degli Studi di Padova, 1979), p. 131.



Recent work established that the dehydration of the decahydrate proceeded in a multi-step fashion. This was confirmed by environmental scanning electron microscopy through the observation of the in situ crystallizing sodium sulfate, its hydration, and its dehydration. The study also confirms that the hydration of sodium sulfate to the decahydrate is much slower and more complex than previously thought. Explanation relying solely on the expansion of the crystal due to hydration, ignores the fact that salts that do not have or can not easily convert to different hydration levels can also cause severe damage. Examples of these types of salts are sodium chloride and gypsum.

It has been recently proposed that the volumetric increases resulting from changes in the concentration of the salt/water system, produce stress at the systems surface boundary by the hydraulic pressure induced by the liquid medium. Using this explanation, it becomes clear how cyclical crystallization of sodium chloride which dissolves easily in little water could cause severe damage. While both of these two

_

A. Elena Charola and Johannes Weber. "The Hydration-Dehydration Mechanism of Sodium Sulphate." in Proceedings of the 7th International Congress on Deterioration and Conservation of Stone, Lisbon, Portugal 15-18 June, 1992, ed. J. Delgado Rodrigues (Lisbon: Laboratorio Nacional de Engenharia Civil, 1992), p. 581-590.

Eric Doelme, "In Situ Dynamic of Sodium Sulfate Hydration and Dehydration in Stone Pores: Observation at High Magnification Using the Environmental Scanning Electron Microscope," in Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994, ed. Vasco Fassina et al. (Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994), p. 143-150.

Antonio Moropoulou and Panagiotis Theoulakis. "Conditions Causing Destructive NaCl Crystallization into the Porous Sandstone, Building Material of the Medieval City of Rhodes," in *The Conservation of Monuments in the Mediterranean Basin Proceedings of the 2nd International Symposium Geneva, 19-21 November 1991*, ed. Daneielle Decrouez et al. (Geneva: Museum d'Histoire Naturelle and Musee d'Art et d'Histoire, 1991), p. 493-499; and K. Zehnder, "New Aspects of Decay Caused by Crystallization of Gypsum," in *Conservation of Stone and Other Materials Volume One Causes of Disorders and Diagnosis Proceedings of the International RILEM UNESCO Congress Paris June 29 - July 1, 1993*, ed. M. J. Thiel (London: E & FN Spon, 1993), p. 107-114.

Joseph Pühringer, "Deterioration of Materials by Hydranlic Pressure in Salt/Water Systems – An Outline Model," in Proceedings of the 8th International Congress on Deterioration and Conservation of Stone



theories may explain in part the damage soluble salts cause, a complete understanding of the decay mechanism of salt crystallization awaits more research. Further, the scenario is complicated significantly when different salts coexist in various combinations and concentrations. Little of the research takes into account the actual conditions within a pore. Most ignore the effect of capillary condensation and the different susceptibility of variously sized pores to salt damage.

2.2 MECHANISMS OF DECAY: OTHER

A. B. Paterakis suggests that calcium sulfate and calcium carbonate can cause the chemical disintegration of some ceramics by the "devitrification of glazes and highly fired ceramic bodies by the leaching of alkalis and dissolution of collodial silica."¹¹ While some salts may lead to the chemical decay of materials, experimentation using bricks illustrates that the damage is negligible when compared to the mechanical decay caused by soluble salts.¹² Because the primary damage caused by soluble salts is in the form of mechanical decay, additional research on this topic would be most useful to the field of building conservation.

In addition to direct decay, salts may increase the rate and severity of other decay mechanisms. Research conducted by Lubica Wessman shows that bricks containing

Berlin, 30 September – 4 October 1996, ed. Joseph Riederer (Berlin: Moller Druck und Verlag, 1996). p. 550.

A. B. Paterakis, "The Deterioration of Ceramics by Soluble Salts and Methods for Monitoring Their Removal," in *Recent Advances in the Conservation and Analysis of Artifacts* (London: Institute of Archaeology, 1987), p. 70.

A. E. Charola and R. J. Koestler, "The Action of Salt-Water Solutions in the Deterioration of the Silicio-Aluminate Matrix of Bricks," in *Il Mattone di Venezia : Contributi Presentati al Concorso di Idee su Patologia, Diagnosi e Terapia del Mattone di Venezia : Ateneo Veneto, Venezia, 29 Ottobre 1982.* (Venezia: Comune di Venezia, 1982), p. 67-76.



salts, especially sodium chloride, are more susceptible to freeze-thaw damage.¹³ Besides increased susceptibility to freeze-thaw deterioration, the change in pore size may lead to an increased susceptibility to capillary rise or capillary condensation. If a relatively insoluble salt, like gypsum, is found in a porous material, the opposite may happen. The open porosity may decrease as a result of pores being blocked by the salt. A resultant decrease in water vapor transmission can then lead to accelerated damage of the material.¹⁴ Finally, the hygroscopic nature of salts leads to a decrease in the drying rate of porous materials, and masonry walls will retain more water, further increasing damage.

2.3 EFFECT ON CONSERVATION TREATMENTS

In addition to increasing the rate of decay of porous materials, soluble salts can interfere with conservation treatments. For example, as described above, less soluble salts, such as gypsum, block surface pores reducing the absorption of consolidants and water repellents. Further, experience and laboratory tests have indicated a significant decrease in the hydrolysis rate of methyl-trimethoxysilane consolidants within porous materials contaminated with sodium sulfate and magnesium.¹⁵

L. Franke and J. Grabau. "Transport of Salt Solutions in Brickwork," in Conservation of Historic Brick Structures Case Studies and Reports of Research, ed. N. S. Baer, S. Fitz, and R. A. Livingston (London: Donliead Publishing Ltd., 1998), p. 167-172.

Lubica Wessman, "Studies of Salt-Frost Attack on Natural Stone." in Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September – 4 October 1996, ed. Joseph Riederer (Berlin: Moller Druck und Verlag, 1996). p. 563-571.

Rakesh Kumar and Clifford A. Price, "The Influence of Salts on the Hydrolysis and Condensation of Methyl-Trimethoxysilane," in *Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994*, ed. Vasco Fassina et al. (Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994), p. 861-865.



2.4 DAMAGE

While the mechanisms of salt decay are not clearly understood, the damage which salts cause is clear. Salts may crystallize either as efflorescence or subflorescence. If the drying rate is slower than the rate of salt solution migration to the surface of the material, then the salts crystallize on the surface. This phenomena is known as efflorescence. While efflorescence does not actively deteriorate the porous body, it can have a dramatic aesthetic impact on the building, compromising its visual integrity.

Subflorescence occurs when the solution in a wall migrates slower than the rate of evaporation resulting in the crystallization of salts just below the surface occur. A major cause of damage, subflorescence is responsible for the flaking, spalling, sugaring, and pitting of porous building materials. Further, in the instance of glazed ceramics, subflorescence results in the loss of cohesion of the pigments and glazes.

Arnold proposes a model for walls where rising damp causes the transportation of the salts. He divides walls into four zones: A, B, C, and D according to the difference in deterioration caused by salt. In this model, Zone A is closest to the soil and represents a wall height up to approximately 0.5 meters. It contains salts with the lowest solubility including calcium carbonate, magnesium carbonate, and calcium sulfate. Zone A shows very few signs of deterioration, when deterioration is present, it is limited to flaking.

Zone B represents the height of the wall between 0.5 and 1 meter. Zone B contains moderately soluble salts including magnesium sulfate, potassium nitrate, sodium

¹⁶ R. Rossi-Manaresi and A. Tucci, "Pore Structure and the Disruptive or Cementing Effect of Satt Crystallization in Various Types of Stone," *Studies in Conservation* Vol. 36 (1991): p. 53.

¹⁷ Andreas Arnold. "Rising Damp and Saline Minerals." p. 11-28.



sulfate, and, in alkaline environments, sodium carbonate. This zone generally has significant efflorescence, and the damage is the most severe. Physical decay in Zone B includes the typical damage associated with soluble salts: granular disintegration, alveolar weathering, and flaking.¹⁸

Higher on the wall, between 1 and 3 meters above the ground, is Zone C. This zone contains the most soluble salts, including sodium chloride, potassium chloride, sodium nitrate, calcium nitrate, and magnesium nitrate. While no clear signs of deterioration exist in this zone, the wall appears darker due to increased amounts of water, a result of the hygroscopic nature of salts. The darkened areas may appear spotted indicating a non-homogeneous distribution of salts. Further, the darkness, i.e. amount of water, will vary depending on the temperature and relative humidity.

Zone D refers to the height above where capillary rise is a problem. It represents the sound wall. This division only serves as a rough guide. There may be substantial differences between the height of each of these zones.¹⁹

2.5 ORIGINS OF SOLUBLE SALTS

The origin of salts in porous material is extremely complex. Furthermore, once inside a porous material, the different ions can recrystallize as different salts. The following provides only a brief outline of the problem; since, the sources must be analyzed on an individual building basis. Defining factors for the type of salts to be found include the geographic location of a building, its environment, and its past history.

¹⁸ Andreas Arnold. "Rising Damp and Saline Minerals." p. 11-28.



Appendix A provides a list of common salts found in historic buildings and their solubilities.

Table 1: Salt Concentration in Sea Water²⁰

Salt	Atlantic Ocean grams / liter	Mediterranean Sea grams / liter	
NaCl	28.14	30.76	
KC1	0.69	0.66	
$MgCl_2$	3.44	3.74	
CaSO ₄	1.42	1.64	
MgSO ₄	2.28	2.39	

Sea water is one of the most commonly cited sources of soluble salts in coastal historic buildings. Table 1 provides the concentration of salts in the Atlantic Ocean and the Mediterranean Sea. The salts found in sea water can infiltrate a building either through rising damp or deposition on the wall surface through salts in the air. The sea is the leading source of chloride salts and may provide substantial amount of sulfate salts. The sea provides a continual source of salts for buildings in its vicinity.

In northern climates, sodium chloride and calcium chlorides can enter into buildings as a result of deicing salts. These salts reduce the freezing point of water, and thus melt the snow and ice. The resulting salt solution is absorbed by capillaries into the wall.

²⁰ Fernand Anger. "World Limestone Decay under Marine Spray and Conditions." p. 65-69.

Another important salt source, atmospheric pollution, either as dry deposition or acid rain, may introduce sulfate or nitrate ions into a building. Sulfate ions can react with sodium ions, deposited by sea water or from some other source, to form the damaging sodium sulfate. Acid rain may also chemically attack calcareous building materials to form gypsum, often found as a black crust. Nitrates only produce highly soluble salts with sodium, potassium, or calcium ions. These can enhance microbiological activity.

Warmer climates promote microbiological growth. These growths can increase sulfate, nitrate, or nitrite deposition on a building surface. Nitrates may also be present in ground soil as a result of decaying organic material.

In many cases, salts are already present in the original building materials, such as sodium sulfate in underfired bricks or alkali sulfates in concrete. They only need water to mobilize and cause damage. Sand obtained from coastal regions for mortar can transfer sea salts into a building during original construction.²¹

Salts may have also been intentionally added to original building materials.

Research from the NATO-CCMS pilot study on brick conservation suggests that sodium chloride may have been deliberately added during the brick-making process in some areas. Early twentieth century sources suggest the use of soluble metallic salts as colorants for glazed terra cotta. Problems with these colorants were recognized even at the time: "we have found in actual practice that our greatest difficulty with soluble salt

11

²¹ R. P. J. van Hees, "Damage Caused by Salts to Curacao-Monuments," in *Structural Repair and Maintenance of Historical Buildings II Proceedings of the Second International Conference Held in Seville, Spain 14-16 May 1991*, ed. C. A. Brebbia et al. (Boston, Computational Mechanics Publications, 1991), p.141-155.



solutions was the fact that they frequently loosened the glaze coat on which they were applied."²³

Incompatible materials placed adjacent to each other may also result in damage from soluble salts. For example, when limestone is placed above terra cotta or siliceous stones such as sandstone and granite, the calcium bicarbonate and calcium sulfate may leach into the ceramic and cause blistering and exfoliation.²⁴

Soluble salts may exist in a building as a result of its use. In an extreme example, a building used for the processing of mined salt was found to be contaminated with sodium and potassium chloride.²⁵ In another example, at Colonial Williamsburg, the source of the sodium chloride deteriorating a brick building was determined to result from its use as a smokehouse.²⁶

Modern interventions into historic structures may also introduce soluble salts.

The use of Portland cement as a replacement mortar for masonry buildings may lead to the development of damaging alkaline salts, commonly found in concrete.²⁷ Previous

²³ A. Lee Bennett, "The Use of Overglazes for Polychrome Terra Cotta." *Journal of the American Ceramics Society*, Vol. 9, No. 4 (April 1926), p. 186.

²² Richard Livingston, Stephen Fitz, and Norbert S., Baer, "The NATO-CCMS Pilot Study on the Conservation of Brick Monuments," in *The Fifth North American Masonry Conference, University of Illinois at Urbana-Champaign June 3-6, 1990* (Boulder: Masonry Society, 1990), p. 805-812.

²⁴ John Fidler. "Fragile Remains: An International Review of Conservation Problems in the Decay and Treatment of Architectural Terracotta and Faience," in Architectural Ceramics: Their History, Manufacture and Conservation A Joint Symposium of English Heritage and the United Kingdom Institute for Conservation 22-25 September 1994 (London: James, 1996), p. 14.

S. Herppich, "Bricks Under the Influence of Huge Salt Immissions Building of a Thuringian Potash Mine," in *Conservation of Historic Brick Structures Case Studies and Reports of Research*, ed. N. S. Baer, S. Fitz, and R. A. Livingston (London: Donhead Publishing Ltd., 1998), p. 477-484.

²⁶ Richard A. Livingston and Thomas H. Taylor Jr., "Diagnosis of Salt Damage at a Smokehouse in Colonial Williamsburg," *APT Bulletin* Vol. XXIII No. 3 (1991): p. 3-12.

Andreas Arnold, "Soluble Salts and Stone Weathering," in *The Conservation of Stone 1 Proceedings of the International Symposium Bologna, June 19-21, 1975*, ed. R. Rossi-Manaresi (Bologna: Centro Per La Conservazione Delle Sculture All'Aperto, 1976), p. 133-135.



conservation treatments, such as the cleaning of architectural ceramics with hydrochloric acid, may result in the eventual formation of soluble salts.²⁸

Archaeological ceramics suffer deterioration from the same salts as buildings.

Their source is most often the ground soil where they were buried. Salts can also exist as a result of the object's original use. Further, many objects on display in museums, stored in hardwood cases, have developed efflorescence of acetate salts as a result of fumes released by the wood.

Clearly, the first crucial step in conserving a building or an object suffering from salt decay is a careful analysis of the salt present and the identification of its source.

Once the source of soluble salts is known, the conservator will be able to make adequate measures for their elimination.

²⁸ Clifford Price, "Stone-decay and Preservation," in Masonry Conservation and Cleaning Handbook ed. Keith Blades et al. (Ottawa: Association For Preservation Technology, 1985), p. 128-131.



3. Conservation

The first step in the conservation of salt-contaminated materials is the identification of the types and sources of salts, and their quantification. Second, further deterioration should be reduced by limiting the water sources or controlling the crystallization of the salts. Finally, if possible, the salts should be removed.

3.1 IDENTIFICATION OF SALTS

The first step to a proper conservation treatment of salt contaminated materials is to identify the salts, a relatively easy step. Microchemical spot tests are the simplest and most economic method for the identification of the specific ions present in the soluble salts. Polarized light microscopy can be further used to determine their actual crystal form and nature. If more information is required analytical techniques such as x-ray diffraction or mineral characterization can be used.

Following salt identification, quantification of the salts could serve to determine the severity of the problem. A simple method of quantification is to soak a ground sample in deionized water and then measure the difference in weight of the dry sample before and after, to obtain a percentage of the total salts. Titrations or ion chromatography can quantify the actual amount of ions present in the resulting solution.

Since salt content is seldom homogenous throughout a wall, as suggested by Arnold's analysis, a suitable number of samples must be taken to get an indication of the salt content in each portion of the wall. Core drill samples should be taken across the wall, at various heights, and at various depths.



Some preliminary work on the smokehouse at Colonial Williamsburg suggests that nondestructive testing using neutron probe can provide reliable results about the salt content, but this technique awaits a clear set of standards and methodologies.²⁹

Once a clear picture of the types and quantity of salts is obtained, a determination of the source of the salts should be made. Soil samples near the structure should be taken to determine the salts present in the soil. Location, environment, history of use, and conservation history should be analyzed. If the salt concentration follows the basic model outlined by Arnold, then capillary rise of ground water is most likely the source of the salts. Atmospheric pollution is probably the source of salts found on the surface. Uniform salt concentration indicates that the building materials may have contained salts originally, or a previous conservation treatment could have left its scar.

3.2 IMMOBILIZATION OF SALTS

Salts are only a problem if they have a water supply and can continue to move and crystallize throughout a building. If the original source of salts no longer exists, no conservation treatment may be necessary, although removal of the salts may be desirable. Often the source of water can be eliminated by routine maintenance, such as cleaning and repairing gutters. If the salts enter the building from the soil through capillary rise of ground moisture more drastic conservation action must take place. The most effective conservation solution so far is to create an impermeable barrier which can stop water infiltration. A mechanical insertion of an impermeable layer, such as metal, has

²⁹ Richard A Livingston and Thomas H. Taylor Jr., "Diagnosis of Salt Damage at a Smokehouse in Colonial Williamsburg." APT Bulletin Vol. XXIII No. 3 (1991): p. 3-12.



successfully been used to stop water infiltration through capillary rise in some historic buildings in Northern Europe.³⁰ Alternatively, chemical barriers such as bitumen emulsions, epoxies, and polyeurathanes can also be used.³¹ Both physical and chemical interventions require destructive intervention to a building. If water is penetrating through the vertically exposed surface of the wall either through rain or condensation, a water repellent could minimize its affect.

Another proposed solution to reduce the mobility and damage, although not recommended, is to form insoluble compounds from the salts. For this purpose, lead fluosilicate has been used. The lead reacts with the anion, either the sulfate ion or the chloride ion, to create less soluble lead sulfate or lead chloride. Magnesium or sodium fluosilicate remain. The reactions are:

$$Na_2SO_4 + PbSiF_6 \cdot 2H_2O \rightarrow PbSO_4 + Na_2SiF_6 + 2H_2O$$

$$MgSO_4 + PbSiF_6 \cdot 2H_2O + 6H_2O \rightarrow PbSO_4 + MgSiF_6 \cdot 6H_2O$$

$$2NaCl + PbSlF_6 \cdot 2H_2O \rightarrow PbCl_2 + Na_2SiF_6 + 2H_2O$$

While still moderately soluble, these fluosilicate are less destructive than the sulfate salts. Alternatively, barium chloride may be injected into the contaminated wall. The reaction is:

$$Na_2SO_4 + BaCl_2 \rightarrow BaSO_4 + 2NaCl$$

 $MgSO_4 + BaCl_2 \rightarrow BaSO_4 + MgCl_2$

1982. (Venezia: Comune di Venezia, 1982), p. 397-435.

³⁰ G. Dingethal, P. Andriolo-Stagno, and H. Weber, "Patologia e Cura Dimurature in Mattoni Danneggiate Dall'Umidita' e Dalla Presenza di Sali," in Il Mattone di Venezia: Contributi Presentati al Concorso di Idee su Patologia, Diagnosi e Terapia del Mattone di Venezia: Aleneo Veneto, Venezia, 29 Ottobre



While this method eliminates the destruction caused by sulfate salts, it still leaves the chloride salts.³² Chemical conversion of damaging soluble salts to insoluble compounds may reduce damage; however, damage will continue as a result of the remaining salts.

Also, the effect of this treatment will dramatically change other characteristics of the building material, such as water vapor transmission. These changes may lead to different decay mechanisms.

3.3 DESALINATION: BUILDINGS

Once intervention has stopped the addition of new soluble salts into a building, an attempt to desalinate the walls may begin. The effectiveness of desalination is difficult to evaluate; hence, further research is necessary to determine how to assess it. Adequate desalination varies with each type of material depending on its environment. For instance, in brick, a sodium chloride content of less than 1.5% by weight may not lead to any damage.³³ In contrast, a chloride content of less than 0.4% in reinforced concrete can cause significant damage due to iron corrosion.³⁴ Further research must be conducted to obtain an idea of what a safe salt content is for each material.

Efflorescence is easier to remove than subflorescence. The least invasive technique to remove efflorescence is simply to brush the salts off of the surface when it appears after crystallization. This technique works best when the salts are loosely

³¹ G. Dingethal, P. Andriolo-Stagno, and H. Weber, "Patologia e Cura Dimurature in Mattoni Danneggiate Dall'Umidita' e Dalla Presenza di Sali," p. 397-435.

³² Helmut Weber, *Mauerfeuchtigkeit: Ursachen und Gegenmaβnahmen*, 2nd Ed. (Sindelfingen, Germany: Expert Verlag, 1984), p. 102-109.

³³ Richard A. Livingston and Thomas H. Taylor Jr., "Diagnosis of Salt Damage at a Smokehouse in Colonial Williamsburg," APT Bulletin Vol. XXIII No. 3 (1991): p. 7.



attached to the original material. Brushing off the salts removes some of the salts from the building, ensuring that they do not reenter the system. While this minimal intervention treatment can improve the aesthetic problems caused by salts, some will remain within the porous material. These remaining salts can continue to crystallize and cause damage.

Another technique used to desalinate walls is simply to flush the surface repeatedly with water.³⁵ In this technique, a fine mist of water is sprayed over the wall, which is then allowed to dry. The treatment is repeated until little new efflorescence appears. Flushing a wall with water supposedly brings the salts from within the wall to the surface. This technique, however, may lead to a rapid deterioration due to increased salt mobility during desalination. Further, if too much water is used or the rate of evaporation is too slow, the salts may be driven further into the wall. If this happens, the salts will remain in the wall continuing to cause damage and making future desalination efforts more difficult.³⁶

Poulticing is a second common desalination technique of salt-contaminated masonry. In this process, a material which dries slowly - either an expansive clay such as attapulgite or bentonite, or a paper poultice - is placed on a dampened wall. Since the drying rate is slower than the rate the salt solution moves to the surface, efflorescence

³⁴ T. P. Lees. "Deterioration Mechanisms," in *Durability of Concrete Structures: Investigation, Repair, Protection*, (New York; E & F. N. Spon, 1992), p. 36.

³⁵ V. Fassina, R. Arbizzani, A. Naccari, and M. Favaro, "Brick Masoury of the Crypt of San Marco Basilica," in *Conservation of Historic Brick Structures Case Studies and Reports of Research*, ed. N. S. Baer, S. Fitz, and R. A. Livingston. (London: Donhead Publishing Ltd., 1998), p. 407-426.

³⁶ J. L. Heiman, "Rising Damp and Salt Attack in Old Masonry," in *Proceedings of the 7th International Brick Conference Melbourne Australia 17-20 February 1985*, ed. Tom McNeilly and John C. Scrivener (Melbourne: University of Melbourne, 1985), p. 240.



occurs. Instead of forming on the surface of the wall, the salts crystallize in the poultice. After the poultice dries, it is removed along with the salts. Like desalination by washing, the initial wetting of the surface during a poultice treatment may drive the salts deeper into the wall, leading to continued salt decay and making future desalination treatments more difficult.³⁷

To decrease the transportation of salts further into the masonry, a technique known as injection poulticing has been used. 38 This technique utilizes pressure transport to desalinate porous materials. A pressure gradient is formed as water injected into the middle of the wall and is forced out through the faces. The technique differs from traditional poulticing in that holes are drilled into the mortar joints of a wall to provide a constant water supply to the center of the wall. A poultice of expansive clay or paper is applied to the wall surface. The rate of transportation by capillary movement to the poultice is greater than the rate of evaporation from the poultice. As a result, the salts crystallize within the poultice; and, when the poultice is removed, the salts are removed with it. Research has indicated injection poulticing successfully removes the salts from the wall in one to four weeks. 30 While this solves the problem of pushing the salts further into the wall, the dampness which injection poulticing creates in the wall may lead to other types of damage. 40

³⁷ P. Friese and A. Protz, "Desalination of Brickwork and Other Porous Media," in *Conservation of Historic Brick Structures Case Studies and Reports of Research*, ed. N. S. Baer, S. Fitz, and R. A. Livingston (London: Donhead Publishing Ltd., 1998), p. 337.

³⁸ P. Friese and A. Protz, "Desalination of Brickwork and Other Porous Media," p. 335-345.

³⁹ P. Friese and A. Protz. "Desalination of Brickwork and Other Porous Media," p. 335-345.

⁴⁰ P. Friese and A. Protz, "Desalination of Brickwork and Other Porous Media," p. 335-345.



Architectural conservators have mainly utilized two long term desalination techniques: 1) sacrificial renders 2) electromigration. Plasters and stuccos have long been used in marine environments susceptible to salt damage as part of their original fabric. Conservators have adopted these sacrificial layers to slow salt damage in buildings, sometimes replacing those which have historically existed. In Venice, a highly permeable salt-resistant stucco has been used on fragile brickwork. Other times, they are added solely as a conservation treatment.⁴¹ A sacrificial stucco was one of four suggested conservation treatments for the salt contaminated smokehouse at Colonial Williamsburg, to shift the salt damage from the brickwork to the stucco.⁴²

This treatment poses some theoretical dilemmas. While adding a sacrificial stucco to a building historically stuccoed may create visual unity within the historic district, at Colonial Williamsburg a stucco would unalterably affect the aesthetic of the building. Further, a stucco can not easily be removed from a building without damage to the substrate.

In electromigration, also called electroosmosis, electrodes with an electric potential are inserted into the masonry. The electrodes may also be connected to the wall so as to create no damage. The speed of desalination is dependent on the electric potential applied and the specific characteristics of the materials. In a German brick

⁴¹ R. Crèvecoeur and H. H. O. Jahn, "The Preservation of Venetian Brickwork by the Use of a Salt Resistant and Vapour Permiable Plaster," in *Il Mattone di Venezia: Contributi Presentati al Concorso di Idee su Patologia, Diagnosi e Terapia del Mattone di Venezia: Ateneo Veneto, Venezia, 29 Ottobre 1982.* (Venezia: Comune di Venezia, 1982), p. 67-76.

⁴² Richard A. Livingston and Thomas H. Taylor Jr., "Diagnosis of Salt Damage at a Smokehouse in Colonial Williamsburg," *APT Bulletin* Vol. XXIII No. 3 (1991): p. 3-12.



house a potential of 50-60 volts was used.⁴³ In a Berlin church, after thirteen years, twenty-five kilograms of salt were removed using this technique. A further ten to twenty years are estimated before desalination is complete.⁴⁴ This technique requires a long time for complete desalination, and further tests are needed to determine its practical applicability to buildings. Although the technique has reported successful in some cases, the overall consensus considers this as a doubtful procedure for salt removal.

Occasionally, a portion of a building can be removed and treated as a discreet object. ⁴⁵ After treatment it can be placed back into its building context. While not a very practical approach, this is sometimes the best approach, especially for significant portions of buildings, as desalination efficiency is greatly improved in movable objects as discussed below.

3. 4 DESALINATION: ARCHAEOLOGICAL CERAMICS

Complete desalination is easier to accomplish in discrete objects. Archaeological ceramics are often found contaminated with a high degree of soluble salts found in the soil. The desalination techniques that can be applied to archaeological ceramics are

⁴³ P. Friese and A. Protz. "Desalination of Brickwork and Other Porous Media." p. 341.

⁴⁴ P. Friese and A. Protz, "Desalination of Brickwork and Other Porous Media." p. 335-345.

⁴⁵ R. Crevecoeur, "The Desalination of a Marble Carved Seat in the Royal Palace, Amsterdam," in *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-27 10 1979.* (Padova: Universita degli Studi di Padova, 1979) p. 471-479; and Vasco Fassina. Rossana Arbizzani, and Andrea Naccari, "Salt Efflorescence on the Marble Slabs of S. Maria Del Miracoli Church: A Survey on Their Origin and on the Methodology of Their Removal," in *Proceedings of the 8th International Congress on deterioration and Conservation of Stone Berlin, 30 September – 4 October 1996*, ed. Joseph Riederer (Berlin: Moller Druck und Verlag, 1996), p. 523-534; and G. Galli, M. Matteini, A. Moles, and C. Manganelli, "Intervento di Desalinazione del Dossale di G. Di Rigino di Verona," in *Deterioration and Preservation of Stones: Proceedings of the* 3rd International Congress (Padova: Università degli Studi, Istituto di Chimica Industriale, 1982), p. 491-499.



based on the same ideas as building desalination. Generally, consolidation either proceeds or follows desalination treatments of ceramics.

Total immersion in deionized water is the most often used desalination technique for archaeological ceramics. On discovery, archaeological ceramics are generally saturated with saline water. In situ emergency conservation generally takes place to ensure that the salts do not immediate crystallize. For this purpose, the objects are generally kept in water until transported to a conservation laboratory. The water used for this immersion is often sea water, so that the osmotic pressure from desalination does not damage the object.⁴⁶

After arrival at a laboratory, the salt content of the water is slowly reduced. The water is then changed in stages: first to drinking water, then to rain water, and finally to deionized water. The process is often monitored using a conductance meter. Within this basic technique there are lots of variations. The most basic question is how much water should be used to desalinate. Conservators suggest that a large amount of water is needed for efficient desalination, from ten to fifteen milliliters of water per gram of object. The second question conservators ask with regard to desalination by total immersion is: what is the necessary frequency to change the immersion water? Some sources suggest that

¹⁶ Colin Pearson (ed.). Conservation of Marine Archaeological Objects. (London: Buttersworth, 1987), p. 257.

J. Ciabach and Slawomir Skibinski. "Analyses of the Total Salt Content and Coutrol of Salt Removal from Stone Historical Objects." in *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989.* ed. Fulvio Zezza (Brescia. Italy: Grafo. 1990), p. 325-328; and Alice Boccia Paterakis and Sarah Nunberg. "The Stabilization of Archaeological Pottery in an Excavation Study Collection through Relative Humidity and Through Desalination." in Le Dessalement des Materiaux Poreux 7es Journees D'Etudes de La SFIIC Poitiers, 9-10 Mai 1996. (Champs-sur-Marne: SFIIC. 1996), p. 137-44.



the water should be continuously changed, while other sources state that changing water once or twice a day is sufficient.⁴⁸

Some sources erroneously suggest that agitation of the solution during desalination increases its efficiency. While continuous stirring may increase the initial rate of desalination, it does not lead to any difference in the total amount of salt removed. The natural convection currents in a solution are strong enough to evenly disperse the salts. Further, continuous agitation can lead to erosion of the ceramic body. Another suggestion, that has been made, is that increasing the temperature of the solution increases the rate of desalination. Again, this technique may lead to severe damage to the ceramics.

If a ceramic artifact is particularly friable, total immersion desalination may damage it. In these cases, desalination with an expansive clay or paper poultice is the preferred treatment. Poultices are applied the same way they are applied to buildings. First the object is wetted. Next a poultice is applied to all exposed surfaces. The poultice is allowed to dry, the time generally ranges from one to four days. The treatment is repeated until adequate desalination is achieved. Poulticing and the total immersion

⁴⁹ Henry W. M. Hodges. "The Conservation Treatment of Ceramics in the Field." in *In Situ Archaeological Conservation: Proceedings of Meetings April 6-13, 1986 Mexico, 1987* (Los Angeles: Getty Conservation Institute, 1986). p. 145.

Alice Boccia Paterakis and Sarah Nunberg. "The Stabilization of Archaeological Pottery in an Excavation Study Collection through Relative Humidity and Through Desalination." in *Le Dessalement des Materiaux Poreux 7es Journees D'Etudes de La SFIIC Poitiers, 9- 10 Mai 1996.*. (Champs-sur-Marne: SFIIC, 1996), p. 137-44; and "Soluble Salts and Deterioration of Archeological Materials." *Conserve O Gram* Number 6/5 (August 1998).

J. L. Antunes. "Characterization of Portuguese 17th Century Tiles." in Proceedings of the International Symposium on Ceramics in Architecture of the 8th CIMTEC-World Ceramics Congress and Forum on New Materials Florence, Italy June 28-July1, 1984. ed. P. Vincenzini (Facnza:L Techna, 1995), p. 658-660.

⁵¹ Henry W. M. Hodges. "The Conservation Treatment of Ceramics in the Field." p. 144-9.



processes can be used in conjunction with one another; a combination of the two has proven successful.⁵²

In the case of sun baked clay cuneiform tablets at the British Museum, the decision to fire the object at higher temperature was chosen before desalination. After firing, the tablets were desalinated by total immersion. This approach ensured the protection of the most important information, the incised designs.

The use of electric potentials, as in electrodialysis, has been successfully applied to objects. As early as the 1930s the technique of electric migration had been used to desalinate ceramics.⁵⁴ Its particular usefulness comes in the ability to direct the movement of the salts. In one case, the salts on archaeological pottery displaced the pigmented surface. Through its appropriate application, this technique directed the salts away from the surface decoration, allowing the pigments to be set back in place and consolidated.⁵⁵

Recently, some questions about the need to desalinate objects placed in a museum have arisen, fearing that desalination will eliminate important organic information about the use and manufacture of ceramics. ⁵⁶ To this end, the regulation of temperature and

-

⁵² P. Andrew Lins. "Technical Notes." in *Dutch Tiles in the Philadelphia Museum of Art*, ed. Jan Daniel van Dam and Pieter Jan Tichelaar, (Philadelphia: Philadelphia Museum of Art. 1984).

⁵³ A. Eric Parkinson, "The Preservation of Cunciform Tablets by Heating to a High Temperature," Museum News (March 1, 1950): p. 6-8.

⁵⁴ Cotin G Fink, "Incrustations on Porous Pottery: A New Method of Cleaning without Loss of Pigment," Technical Studies Vol. 2 (1933-4): p. 59-61.

⁵⁵ Cotin G. Fink. "Incrustations on Porous Pottery: A New Method of Cleaning without Loss of Pigment." p. 59-61.

Denise Ling and Sandra Smith, "To Desalinate or not to Desalinate? That is the Question," in Le Dessalement des Materiaux Poreux 7es Journees D'Etudes de La SFHC Poitiers, 9- 10 Mai 1996, (Champs-sur-Marne: SFHC, 1996), p. 65-74.

relative humidity has recently gained popularity as a minimal conservation treatment.⁵⁻
Recent research, however, has shown that, salt can continue to cause damage even with minimal RH fluctuations below the critical RH.⁵⁸ Any decision to leave soluble salts in a archaeological ceramic, even if in a museum where the environment can be regulated, must be made cautiously.

Conservators have also increasingly discussed the question: what is a safe level of salt content? Each conservator has chosen a different ending point for desalination. In the total immersion technique, the suggested endpoint ranges from when the conductance of the water is less than 50 microsiemens to less than 1000 microsiemens. ⁵⁹ It is necessary, however, to correlate this measurement with the total volume of solution. The necessary desalination, like in buildings, will depend on the characteristics and the condition of the material. More research must be undertaken to decide what level of desalination provides adequate removal of soluble salts.

⁵⁷ Alice Boccia Paterakis and Sarah Nunberg. "The Stabilization of Archaeological Pottery in an Excavation Study Collection through Relative Humidity and Through Desalination," in *Le Dessalement des Materiaux Poreux 7es Journees D'Etudes de La SFIIC Poitiers*, 9- 10 Mai 1996, (Champs-sur-Marne; SFIIC, 1996), p. 137-44.

⁵⁸ A. Elena Charola and Sara Nunberg. "Soluble Salts in Ceramic Bodies: Deterioration Due to Minimal Changes in Relative Humidity," Manuscript to be submitted to *Studies in Conservation*.

⁵⁹ J. Olive and C. Pearson. "The Conservation of Ceramics from Marine Archaeological Sources." in Preprints of the Contributions to the Stockholm Congress 2- 6 June 1975 Conservation in Archaeology and the Applied Arts (London: International Institute for Conservation, 1975), p. 63-68; and A. B. Paterakis. "The Deterioration of Ceramics by Soluble Salts and Methods for Monitoring Their Removal." in Recent Advances in the Conservation and Analysis of Artifacts (London: Institute of Archaeology, 1987), p. 67-73.



4. CHARACTERIZATION OF TILES

To test the relationship between porosity and desalination efficiency, two sets of tiles with different porosities were chosen. The porosities of these tiles are similar to the range frequently found in both architectural and archeological ceramics.

The red earthenware tiles (Munsell 10R Hue, 5 Value, 6 Chroma) used for the experimentation were manufactured by extruding a six by six centimeter slab of Ohio Red Art earthenware clay and slicing one and a half centimeter thick tiles from it. The earthenware tiles were fired at 800 °C (cone 015). After firing, the tiles measured an average of 5.7 centimeters by 5.6 centimeters by 1.4 centimeters and had an average weight of 71.61 grams. The tiles were friable and some formed hairline cracks along the edges during the experimentation.

The open porosity of the earthenware tiles was determined by twenty-four hour immersion (ASTM C67-97) in deionized water. A percent of the difference between dry and saturated weight was then calculated. The average weight gain of the four tested tiles was 17.7%, as shown in Table 2. During this test some dissagregation of the tiles occurred, but this had no significant effect on the calculations. The test was repeated with a five hour immersion in boiling water (ASTM C67-97). The average weight increase by this technique was 19.1%. During boiling immersion, three of the four tiles cracked and broke (Tiles A, C, and D). The test was continued, but these show a lower percent of weight gain than Tile B which remained intact. The pores were further characterized using optical microscopy to examine thin sections. A large number of



pores ranging from an area of 0.05 mm² to 0.0001 mm² were found. Appendix B lists the pore measurements in the earthenware tiles.

Table 2: Porosity of Earthenware Tiles

Tile	Porosity percent weight gain	Boiling percent weight gain	
A	16.9%	18.3%	
В	17.9%	20.2%	
С	18.7%	19.3%	
D	17.1%	18.7%	
Average	17.7%	19.1%	

This distribution of large and medium sized pores make the tiles susceptible to salt decay.

The high porosity is a result of a large pore area and the interconnectedness of the pores.

The small difference in weight gained during the boiling immersion test shows that few very small pores exist.

The mineralogical characterization of the earthenware tiles was carried out by polarized light microscopy of thin sections (Figures 1-4). As expected, all of the identifiable minerals are silicates. Approximately 15% of the sample was small quartz grains. Identified by their sharp angular shape and 90° extinction angle, the quartz grains were well sifted with most having both a major and minor axis of 2.3 x 10⁻⁴ millimeters. There were also some very fine grains of quartz, only distinguishable at magnifications greater than 100 times. A minimal amount of plagioclase feldspars were identified by their lamelar twinning.

`




Figure 1: Photomicrograph of Earthenware Tile Thin Section in Transmitted Light (Magnification 25x).




Figure 2: Photomicrograph of Earthenware Tile Thin Section under Cross Polarized Light (Magnification 25x).




Figure 3: Photomicrograph of Earthenware Tile Thin Section in Transmitted Light (Magnification 100x).




Figure 4: Photomicrograph of Earthenware Tile Thin Section in Crossed Polarized Light (Magnification 100x).

The grains were held together by a very fine grained red matrix composed of clays and the very fine quartz grains. Figures 1-4 show the general appearance of this material.

The yellow-pink stoneware tiles (Munsell 7.5YR Hue, 7 Value, 4 Chroma) were made by extruding a six by six centimeter clay slab of stoneware clay. They were fired at 1230 °C (cone 06). After firing, the average dimensions of the tiles were 5.3 centimeters by 5.4 centimeters by 1.4 centimeters, and the average weight of the stoneware tiles was 76.90 grams. These tiles were hard, and salt crystallization caused little damage.

The open porosity of the stoneware tiles was also determined by twenty-four hour immersion (ASTM C67-97) and five hour immersion in boiling water (ASTM C67-97). The results are given in Table 3. The open porosity of the stoneware tiles was significantly lower than that of the earthenware tiles. Further, a greater weight increase occurred during the boiling immersion experiment than did in the earthenware tiles, indicating a greater amount of very small pores.

Table 3: Porosity of Stoneware Tiles

Tile	Porosity	Boiling	
A	5.3%	8.2%	
В	4.6%	7.5%	
С	5.3%	7.8%	
D	5.0%	7.6%	
Average	5.1%	7.8%	




Figure 5: Photomicrograph of Stoneware Tile Thin Section in Transmitted Light (Magnification 25x).




Figure 6: Photomicrograph of Stoneware Tile Thin Section under Cross Polarized Light.




Figure 7: Photomicrograph of Stoneware Tile Thin Section under Transmitted Light (Magnification 100x).




Figure 8: Photomicrograph of Stoneware Tile Thin Section under Cross Polarized Light (Magnification 100x).




Pore characterization was carried out with microscopic analysis of thin sections (Figures 5-8). The measurements are provided in Appendix C. While the stoneware tiles had a much lower porosity, most of the pore area was a result of a small number of large pores. Unlike the earthenware tiles; however, there were few medium sized pores. The long and narrow pore shape in the stoneware is a result of the extrusion manufacturing process.

Polarized light microscopy was also used for mineralogical characterization of the stoneware tiles. As in the case of the earthenware tiles, silicate minerals predominated. The stoneware tiles had fewer but larger quartz grains than did the earthenware tiles. The quartz grains were well sifted with an average major and minor axis of 8.8 x 10⁻⁴ millimeters. Quartz comprised approximately 10% of the total area. The rest of the stoneware tiles was a fine grained gray clay matrix under transmitted light and browngray under cross polarized light. The clay also formed larger colloidal aggregates with small quartz grains within them. The clay was powdered and the refractive index was determined to be 1.56 using a collection of refractive index oils. Based on these observations, and the low first order interference color, the clay was determined to be kaolinite, a clay often used in the manufacture of tiles.


The drying rate of both tiles was determined according to NORMAL 29/88 and plotted in Graphs 1 and 2. The results confirm the observation of pore size determined by optical microscopy. The initial drying rate of the stoneware tiles was faster than the earthenware tiles because of the larger pores. The complete drying, however, took longer because of the finer pores evident in the boiling porosity test.



Graph 1: Drying Rate of Earthenware Tile



Graph 2: Drying Rate of Stoneware Tiles





The earthenware had a consistent drying rate because of the interconnectedness of the pores, as indicated by the porosity measurements.

While both tiles had similar mineralogical compositions, their properties most notably open porosity and pore sizes were notably different. These characteristics had a tremendous effect on the desalination efficiency of the tiles.



5. ANALYTICAL TECHNIQUES

Conductance measurements and conductimetric titrations were chosen to quantitatively evaluate the amount of salts removed from the sets of tiles. Both of these techniques have the advantage of using simple and inexpensive instrumentation. Easy to interpret, the results can be extremely accurate. Both methods rest on the measurement of conductivity.

Conductivity is the ability of a solution to carry electricity due to the mobility of ions when subjected to an electric field. Most simply, conductance is the inverse of resistance. Conductance of a solution depends on the concentration of ions, and the specific ion's mobility, size, and valence. Conductance measurements are most suited for strong electrolytes because of the complete dissociation of the molecules. Sodium chloride, sodium sulfate, and gypsum are all strong electrolytes. Table 4 gives the equivalent conductance for the ions in question.

Table 4: Equivalent Ion Conductance at 25° C⁶⁰

lon	λ
Na ⁺	50.1
Cl	76.3
Ag^+	61.9
NO ₃ Na ⁺	71.4
Na ⁺	50.1
1/2SO ₄ ²⁻	79.8
1/2Ca ²⁺	79.8 59.5 63.6
1/2Ba ²⁺	63.6

36

⁶⁰ Donald T. Sawyer, William R. Heineman, and Janice M. Beebe, *Chemistry Experiments for Instrumental Methods* (New York: John Wiley & Sons, 1984), p.59.



5.1 TITRATIONS

Titrations involve the addition of a solution of known concentration, the titrant, to a solution of unknown concentration, the titrand. When an equivalent number of moles of titrant to the titrand have been added the endpoint has been reached marking the end of the reaction. This may be monitored using a colored indicator, or measuring changes in pH or conductance. A conductimetric titration specifically uses conductance to identify the endpoint. Since conductance readings are very sensitive, it is an ideal technique to mark the endpoint of a titration. Further, unlike using pH, the titration endpoint is calculated based on a number of readings, not requiring the measurement of the actual endpoint. This use of multiple readings reduces the difference between the equivalence endpoint and the visible endpoint that sometimes exist. As a result, the data is more accurate and less subject to technical or operator error than other titration techniques.

To evaluate the amount of salts present, two different titrants are used. First, silver nitrate is used to measure the concentration of chloride ions. Second, barium chloride is used to evaluate the concentration of sulfate ions.

Argentometric titrations utilize silver nitrate as the titrant because silver ions react rapidly with chloride ions. The reaction is:

$$Ag^{+} + NO_{3}^{-} + Na^{+} + Cl^{-} \rightarrow AgCl + Na^{+} + NO_{3}^{-}$$

The chloride ions precipitate with the silver ions, removing their contributing conductance and lowering the total conductance of the solution. Since the silver ion added also precipitates, it does not affect the conductance readings. The nitrate ion, however, remains in the solution and contributes to an increase in the total conductance.



Since the equivalent ionic conductance of the nitrate being added is slightly larger than the chloride ion being subtracted, the conductance of the solution increases minimally while the nitrate ion's contribution replaces the chloride ion's. Once all the chloride ions have completely reacted with the silver ions (the endpoint) the addition of more silver nitrate will increase the conductance of the solution more rapidly; since, both silver and nitrate ions will be adding conductance, and no ion is being removed from the solution.

Conductance varies greatly with concentration so that when the titrant is added the concentration of the solution decreases. This change in volume can be compensated for by multiplying the measured conductance against the correction factor $(V \pm v)/V$ where V equals the milliliters of initial volume, and v equals the milliliters of titrant added to the solution.⁶¹

Temperature also affects conductance by approximately 2.5% per degree Celsius.⁶² The best way to minimize this effect is to keep the solution in a hot oil bath which regulates the temperature within 0.01 °C. For the present experiments given the number of measurements taken, it was sufficient to keep the temperature constant to 1°C. This was achieved by a water bath at room temperature.⁶³

Given the linear relationship between conductance and concentration, when the results are plotted as conductance against milliliters of titrant added, the result will be two

62 Donald T. Sawyer, William R. Heineman, and Janice M. Beebe. *Chemistry Experiments for Instrumental*

Methods, p.63,

38

⁶¹ F. W. Fifield and D. Kealey, *Principles and Practice of Analytical Chemistry* 2nd Edition (London: International Textbook Company Limited, 1983), p. 227; and Donald T. Sawyer, William R. Heineman, and Janice M. Beebe, *Chemistry Experiments for Instrumental Methods*, p. 63.



lines. The first line will have a slope of near zero. The slope of the second line will be positive. The endpoint will be determined by the intersection of these two lines. The points close to either side of the endpoint should be ignored when drawing the lines. In this region of the graph, curvature may occur as a result of the partial disassociation of the precipitates. This curvature can be minimized by using the titrant at the strongest possible concentration. After determining the endpoint, the number of equivalent moles of sodium chloride can be determined, and from it, the concentration or the weight of the salt in the solution can be calculated

Barium chloride is used to titrate either the sodium sulfate or the gypsum in these experiments. The two reactions are:

$$2Na^{+} + SO_{4}^{2-} + Ba^{2+} + 2Cl^{-} \rightarrow BaSO_{4} + 2Na^{+} + 2Cl^{-}$$

$$Ca^{2-} + SO_4^{2-} + Ba^{2+} + 2Cl^- \rightarrow BaSO_4 + Ca^{2+} + 2Cl^-$$

The result is very similar to the titration with silver nitrate. In both of the reactions, sulfate ions are removed from the solution, and chloride ions are added. There is no appreciable difference in conductance until there are no more sulfate ions present to react with the barium. At this point, conductance increases rapidly. Again, two lines are drawn once the points are plotted. The intersection of these two lines indicates the endpoint of the titration. The concentration of either of the sulfate salts can then be determined.

39

Ralph N. Adams et al., Treatise on Analytical Chemistry Part I Theory and Practice Volume 4 Section D-2 Electrical Methods of Analysis Chapter 42-5 (Easton, PA: John Wiley & Sons, 1963), p. 2579.
 F. W. Fifield and D. Kealey, Principles and Practice of Analytical Chemistry 2nd Edition, p. 218.



In order for an accurate precipitation titration to occur, the reaction must be fast and simple. Further, the resulting compound must be very insoluble. Table 5 lists the solubilities of the precipitates. Both silver chloride and barium sulfate are insoluble at room temperature.

Table 5: Solubility of Precipitates⁶⁶

Salt	K _{sp at} 25°C	Grams per 100ml of water
Silver chloride	1.56 x 10 ⁻¹⁰	0.000089 g (0°C)
Barium sulfate	1.08 x 10 ⁻¹⁰	0.000246 g (25°C)
Silver sulfate		0.57 g (0°C)

However silver sulfate is also fairly insoluble, so that the procedure was tested to determine whether this method would represent an error in solutions when both anions are present.

5.2 TEST TITRATIONS

Test titration of a series of known standards were carried out before titration of unknowns to verify the accuracy of the technique and to quantify the potential error. In the first set of test titrations, the three salts sodium chloride, sodium sulfate, and gypsum were titrated in isolation (Table 6 and Graphs 3, 4, and 5).


⁶⁶ Robert C. Weast (ed.). "Physical Constants of Inorganic Compounds." *CRC Handbook of Chemistry and Physics* 58th Edition (Cleveland: CRC Press, 1978). p. B-83-B178.

⁶⁵ Ralph N. Adam et al. Treatise on Analytical Chemistry Part I Theory and Practice Volume 4 Section D-2 Electrical Methods of Analysis Chapter 42-5, p. 2616.




Test Titrations of Single Salts: Volume of Titrant vs. Conductance (K)


Graph 3: Chloride with Silver Nitrate



Graph 4: Sodium Sulfate with Barium Chloride



Graph 5: Gypsum with Barium Chloride





Solutions of 100 milliliters were prepared and titrated. The titration of the sodium chloride showed the highest degree of accuracy, accurate to 0.0001 grams per 100 milliliters (Graph 3). The titration of gypsum was the least accurate, accurate to 2 milligrams per 100 milliliters (Graph 5).

Table 6: Test Titrations of Single Salts

Titration	Calculated Endpoint	Titration Endpoint	Molarity determined by Titration	Difference between calculated molarity and molarity determined by Titration	Difference in grams of salt between calculated grams and grams determined by titration
100ml of 0.01M NaCl with 0.1M AgNO ₃	10.0 ml	9.84 ml	0.0098 M	-0.002 M	00012 g
100ml of 0.00625M Na2SO4 with 0.05BaCl ₂	12.5 ml	12.0 ml	0.006 M	-0.0025 M	00036 g
100ml of 0.0025M Gypsum with 0.05M BaCl ₂	5.0 ml	4.7 ml	0.0024 M	-0.0001 M	0017 g


All three titrations of the single salts had a reading just below the calculated salt concentration.

The next series of titrations were tested for sodium chloride content when mixed with sodium sulfate (Table 7 and Graphs 6, 7, and 8). Unlike the test of sodium chloride in isolation, each one of these tests slightly overestimated the sodium chloride concentrations.




Test Titrations of Sodium Chloride in the Presence of Sodium Sulfate: Volume of Silver Nitrate vs. Conductance (K)


Graph 6: In the Presence of 0.00625M Sodium Sulfate



Graph 7: In the Presence of 0.00125M Sodium Sulfate



Graph: 8: In the Presence of 0.00625M Sodium Sulfate





The test titration for sodium chloride in the most concentrated solution of sodium sulfate (0.00625 M) provided the least accurate results, 0.0056 grams above the calculated sodium chloride content (Table 7 and Graph 4). The endpoint of this graph is not as sharp as the single salt solution titrations. The curvature at the endpoint is a result of a small amount of silver ions reacting with the sulfate ions to form silver sulfate.

Table 7: Test Titrations of Sodium Chloride with Sodium Sulfate

Titration	Calculated Endpoint	Titration Endpoint	Molarity determined by Titration	Difference between catculated motarity and motarity determined by Titration	Difference in grams of salt between calculated grams and grams determined by titration
100mt of 0.00625M NaC1 and 0.00625 Na ₂ SO ₄ with 0.1M AgNO ₃	6.25 ml	7.15 mt	0,0072 M	0.00095 M	0,0056 g
100ml of 0.00625M NaCl and 0.00125M Na ₂ SO ₄ with 0.1M AgNO ₃	6.25 ml	6.30 ml	0.0063 M	0.00005 M	0,0003 g
100mt of 0.00125M NaCt and 0.00625M Na ₂ SO ₄ with 0.0141M AgNO ₃	8.9 ml	9.0 ml	0.001 M	0.00025 M	0.0015 g

This error was not considered significant; since, this condition was unlikely to occur in the desalination solutions. The quantity of sodium chloride was always higher than the quantity of sodium sulfate during desalination due to the higher solubility of sodium



chloride. Approximately 77% of the total salt content of those tiles containing both sodium chloride and sodium sulfate was sodium chloride. Graph 8 shows the successful titration of a solution containing smaller amounts of sodium chloride,0.00125 M. To titrate this solution, a titrant of lower concentration was used, 0.0141 M silver nitrate. While the slope of the second half of the titration curve has a smaller slope than the slope in the graphs using 0.1 M silver nitrate, the results were still accurate. Because of the large quantity of sodium chloride in the tiles, it was not generally necessary to use such a dilute titrant.

In the third set of test titrations, the sodium chloride content was tested for in the presence of gypsum (Table 8 and Graphs 9, 10, and 11).


Table 8: Test Titrations of Sodium Chloride with Gypsum

Titration	Calculated Endpoint	Titration Endpoint	Molarity determined by Titration	Difference between calculated molarity and molarity determined by Titration	Difference in grams of salt between calculated grams and grams determined by titration
100ml of 0.00625M NaCl 0.000625 Gypsum with 0.1M AgNO3	6.25 ml	5.46 ml	0.0055 M	-0.007 M	-0.0044 g
100ml of 0.00625M NaCl 0.000125 Gypsum with 0.1M AgNO3	6.25 ml	6.2 ml	0.0062 M	-0.00005 M	-0.00029 g
100ml of 0.005M NaCl 0.0025 Gypsum with 0.1M AgNO3	5.0 ml	4.8 ml	0.0048 M	-0.0002 M	-0.0011 g




Test Titrations of Sodium Chloride in the Presence of Gypsum: Volume of Silver Nitrate vs. Conductance (K)


Graph 9: In the Presence of 0.000625M Gypsum



Graph 10: In the Presence of 0.000125M Gypsum



Graph 11: In the Presence of 0.0025M Gypsum




Since the solubility of gypsum is so much lower than that of sodium chloride, all of the solutions tested had a greater amount of sodium chloride than gypsum. All three titrations gave accurate results within a few milligrams. Like the single salt test titrations, the results understated the calculated content of sodium chloride. The gypsum did not have any effect on the titration of the sodium chloride.

The fourth set of test titrations were used to verify the ability to determine the concentration of sodium sulfate in a sodium chloride solution (Table 9 and Graphs 12, 13, and 14). Again, the results show good accuracy. The difference between the calculated amount of grams and the titration amount of grams was within a few milligrams. All of these titrations gave a sodium sulfate concentration slightly higher than expected. Graph 13 illustrates the ability to determine the sodium sulfate content using a less concentrated titrant, 0.005M barium chloride. Just like the titrations using a titrant of a lower concentration of silver nitrate, the endpoint is less clear because the slope of the titration curve is smaller. In general, titrations for sodium sulfate when present with sodium chloride were not undertaken; since, estimating the concentration based on the conductance to molarity correlation curves gave accurate results.




Test Titrations of Sodium Sulfate in the Presence of Sodium Chloride: Volume of Titrant vs. Conductance (K)

Graph 12: In the Presence of 0.00625M Sodium Chloride



Graph 13: In the Presence of 0.00625M Sodium Chloride



Graph 14: In the Presence of 0.00125M Sodium Chloride






Table 9: Test Titrations of Sodium Sulfate with Sodium Chloride

Titration	Calculated Endpoint	Titration Endpoint	Molarity determined by Titration	Difference between calculated molarity and molarity determined by Titration	Difference in grams of salt between calculated grams and grams determined by titration
100ml of 0.00625M Na2SO4 and 0.00625 NaCl with 0.05M Barium Chloride	12.5 ml	13.3 ml	0.0067 M	0,00045 M	0.0064 g
100ml of 0.00125M Na2SO4 and 0.00625 NaCl with 0.005M Barium Chloride	25 ml	27 ml	0.0014 M	0,000 1 5 M	0.0021 g
100ml of 0.00625M Na2SO4 and 0.00125 NaCl with 0.05M Barium Chloride	12.5 ml	12.7 ml	0.006 4 M	0.00015 M	0.0021 g


The final set of test titrations determined the concentration of gypsum within a sodium chloride solution (Table 10 and Graphs 15, 16, and 17). The results of Graphs 15 and 16 show the ability to determine the gypsum content when it is at least 0.0025 M.

Graph 17 shows the results of a titration when the concentration of the titrand is too low. The two lines which are drawn do not intersect. The endpoint of the titration can not be determined; the conductance from the sodium chloride overwhelms any change due to the precipitation of barium sulfate.




Test Titrations of Gypsum in the Presence of Sodium Chloride: Volume of Titrant vs. Conductance (K)

Graph 15: In the Presence of 0.025M Sodium Chloride



Graph 16: In the Presence of 0.005M Sodium Chloride



Graph 17: In the Presence of 0.025M Sodium Chloride






Table 10: Test Titrations of Gypsum with Sodium Chloride

Titration	Calculated Endpoint	Titration Endpoint	Molarity determined by Titration	Difference between calculated molarity and molarity determined by Titration	Difference in grams of salt between calculated grams and grams determined by titration
100ml of 0.0025M Gypsum and.025M NaCl Titrated with 0.05M BaCl2	5.0 ml	5.0 ml	0.0025 M	0.0 M	0.0 g
100ml of 0.0025M Gypsum and.005M NaCl Titrated with 0.05M BaCl2	5.0 ml	4.8 ml	0.0024 M	-0.0001 M	-0.0017 g
100ml of 0.0005M Gypsum and.025M NaCl Titrated with 0.005M BaCl2	10 ml	No clear endpoint	No determination possible.	No determination possible.	No determination possible.

The titration of gypsum within a sodium chloride solution was not generally necessary; since, an accurate quantification could be obtained from the molarity to conductance correlation curve.

These five sets of test titrations clearly show that an accurate quantification of both chloride and sulfate salts can be determined when the two types of salts are found together. The solutions tested were combinations that are beyond the range likely to occur during desalination, but even in these extreme cases accurate results were obtained.



5.3 Calibration Curves


Conductance measurements were carried out on standard solutions at ambient lab conditions. The temperature ranged from 17 to 22 °C. The relative humidity ranged from 25% to 35% RH. With standard solutions of sodium chloride, sodium sulfate, and gypsum, calibration curves to correlate conductance to molarity were obtained. These curves were used to estimate the concentration of the salts. The sodium chloride solutions were prepared from a purchased standard 0.1 M solution. The sodium sulfate and gypsum solutions were prepared in the laboratory. All three conductance to molarity correlation curves illustrate the linear relationship between concentration and conductance (Graphs 18, 19, and 20).

5.4 TITRATION PROCEDURE

The test titrations indicated that a titration curve with a clear endpoint could be obtained by titrating one hundred milliliters of a 0.01 M solution of sodium chloride with a 0.1 M solution of silver nitrate. This concentration provided enough points before the endpoint to get the correct slope of the first conductance line. The endpoint would be at approximately ten milliliters. An accurate line could not be obtained using a solution with a concentration of less than a 0.00125 molar sodium chloride. By appropriately diluting an aliquot of the solution in which the tile was immersed, the titrand was prepared. For the earthenware tiles, it was occasionally necessary to dilute the solution twice.




Graph 18: Sodium Chloride Conductance (K) Standardization Curve






Graph 19: Sodium Sulfate Conductance (K) Standardization Curve





Graph 20: Gypsum Conductance (K) Standardization Curve





The test titrations for the sulfate salts indicated that one hundred milliliters of a 0.005 molar solution titrated with 0.05 molar barium chloride gave the most accurate results. This titrand was prepared and titrated.

For both titrations, a smaller volume of a more concentrated titrand could have been used, but the volume correction necessary for such titrations was far larger.

Once prepared, the solution was placed in a water bath, to regulate the temperature during the titration. A magnet was placed in the beaker with the solution, and the water bath and beaker were placed on top of the magnetic stirrer. The stirrer was set at a low speed. The calibrated conductance cell was placed in the solution and a reading was taken. The titrant was added one milliliter at a time from a twenty-five milliliter graduated burette. For titrating the chloride ions, fifteen to thirty seconds after each milliliter was added a conductance reading was taken. For the sulfate ion titrations the response was slower so the reading was taken after thirty to sixty seconds. After three equal successive measurements, the reaction was considered complete. The conductance value was recorded in microsiemens, and another milliliter of titrant was added.

The endpoint was immediately noticeable by the increase in the conductance reading. Another five to ten milliliters were added beyond the endpoint to have a suitable number of points to draw the titration curve.

The data from the titration was plotted with the conductance value along the y-axis and milliliters of titrant added along the x-axis. The actual conductance was multiplied by the volume correction value $(V\pm v)/V$ where V equals the initial volume



and v equals the number of milliliters added to the solution.⁶⁷ The resulting conductance values were plotted on the same graph as the uncorrected values. Using Microsoft Excel two trend lines were drawn omitting the values near the endpoint. The endpoint was determined by the intersection of the two trend lines. From the endpoint the molarity of the initial solution was determined. This molarity was translated to the total grams of salt in the solution.

When two salts were in combination, the procedure was as follows. First, the total conductivity of the solution was measured. Since, the concentration of the sodium chloride was far larger - nearly one order of magnitude greater than for sodium sulfate and almost two orders of magnitude greater than for gypsum - it contributed most of the conductance. The total conductance was used to estimate the molarity of sodium chloride so as to prepare the titrand. An aliquot of this solution was then diluted and titrated for chloride ions first. Using the conductance to molarity correlation curve for sodium chloride, the contributing conductance of the sodium chloride was determined. This contributing conductance was subtracted from the initial total conductivity measured. The sulfate salt was responsible for the remaining conductance. Using the subtracted conductance, the concentration of the sulfate salt was determined using the conductance to molarity calibration curve. If the concentration of the sulfate ion was large enough, the solution was titrated to confirm its concentration. Theoretically, relying on the conductance to molarity correlation curve, for the concentration of the sulfate salts in the

⁶⁷ F. W. Fifield and D. Kealey, *Principles and Practice of Analytical Chemistry* 2nd Edition, p. 227; and Donald T. Sawyer, William R. Heineman, and Janice M. Beebe, *Chemistry Experiments for Instrumental Methods*, p. 63.



presence of sodium chloride, underestimates the actual concentration because of interion interaction.⁶⁸ This difference is minimal in solutions of extremely low molarity. The accuracy of this technique was tested empirically. The results are shown in Table 11.

Table 11: Test Titrations of Conductance Estimated Concentrations

Solution	Salt	Titration Molarity	Conductance Estimated Molarity	Titration Grams Removed in 150ml solution	Conductance Grams Removed 150ml Solution
Tile E10 Solution 1	Sodium Sulfate	0.0185 M	0.015 M	0.39 g	0.32 g
Tile E10 Solution 2	Sodium Sulfate	0.003 M	0.0028 M	0.064 g	0.06 g
Tile E10 Solution 3	Sodium Sulfate	0.003 M	0.003 M	0.064 g	0.0064 g
Tile E26 Solution 1	Sodium Sulfate	0.02 M	0.018 M	0.43 g	0.38 g
Tile S45 Solution 2	Gypsum	0.0009 M	0.0008 M	0.02 g	0.02 g

D. B. Hibbertand A. M. James, Dictionary of Electrochemistry Second Edition, (New York: John Wiley & Sons, 1984), p. 52.



6. DESALINATION TESTS

6.1 INTRODUCTION

Initial experimentation began by testing the tiles which only contained a single salt: sodium chloride, sodium sulfate, or gypsum. During this stage, the difference between salt removal from porous, friable, low-fired earthenware tiles and hard, less porous, high fired stoneware tiles was compared. Also, a comparison was made between the removal of the different salts in isolation. The results for the stoneware tiles impregnated with gypsum are not accurate given the combination of the low solubility of the salt and the low open porosity of the tile. Since the measurements were of the order of the experimental error, the results for these tests are not reported.

6.2 PROLONGED IMMERSION

The first method tested was simply the soaking of tiles in 150ml of deionized water. One hundred and fifty milliliters was chosen as the minimum amount of water necessary to cover a single tile placed in a 250ml beaker, the smallest beaker the tile could fit into. The tile sat on its edge resting against the side of the beaker to allow the water currents to disperse the salts. The tile was placed into a previously filled beaker. The beaker was covered and conductance measurements were taken every hour for the first eight hours and daily afterwards. Some texts suggest climatizing the tile in a environment with a relative humidity of 100% before immersion into the water, to



eliminate trapped air within the tile, 69 but the similarity in the porosity of the tiles with total immersion and boiling (Tables 2 and 3) indicated this extra step was not required; since, water at room temperature infiltrated most open pores.

In the case of the earthenware tile containing sodium chloride, after two and a half hours the conductance of the solution went beyond the range of the conductance meter used (19,990 microsiemens). In order to continue to monitor the salt removal, the solution was changed at that time. When the increase of conductance of two successive readings within twenty-four hours was minimal the soaking cycle was ended. The earthenware tiles remained in the 150ml of water for ten days. The stoneware tiles remained in the solution for eight days.

Table 12: Percent of Salts by Prolonged Immersion in 150 milliliters of Water

Salt	Percent of Total Salts Removed
NaCl	96.2%
Na ₂ SO ₄	85.6%
Gypsum	70.8%
NaCl	86.9%
Na ₂ SO ₄	76.0%
	NaCl Na ₂ SO ₄ Gypsum NaCl

The results clearly show two trends (Table 12). First, all salts were more easily removed from the earthenware tiles than from the stoneware tiles. This relates to the difference between the total porosity and pore size distribution of the two sets of tiles.

⁶⁹ Colin Pearson (ed.). Conservation of Marine Archaeological Objects, (London: Buttersworth, 1987). p.



Second, the sodium chloride is easiest to remove followed by the sodium sulfate. The removal of the gypsum was the most difficult. This difference is a result of the difference in the solubility of the salts.

Many sources suggest that a large amount of water is needed to effectively desalinate objects. A typical suggestion is that 10 milliliters of water is needed for every 1 gram of object to be washed. To test the hypothesis that a large amount of water is necessary to desalinate salts from ceramics, the first experiment was repeated using 300 milliliters instead of 150 milliliters of deionized water (Table 13). The tiles were set on glass beads to allow for the circulation of the solutions. Tiles were chosen with the closest amount of total salts as their counterparts had in the first Experiment. Again, for the earthenware tile treated with sodium chloride. tile E63, the solution was changed after seventy-two hours because the conductance of the solution surpassed the range of the conductance meter.


The results, summarized in Graphs 21 and 22, disproved the hypothesis that a large volume of wash solution is necessary. There was no significant difference between these two tests. The amount of water used does not significantly alter the efficiency of desalination. The results show the same correlation as the first experiment, the removal of salts as a function of tile porosity and salt solubility.

^{257.}

⁷⁰ J Ciabach and Slawomir Skibinski. "Analyses of the Total Salt Content and Control of Salt Removal from Stone Historical Objects." in The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989, ed. Fulvio Zezza (Brescia, Italy: Grafo, 1990), p. 325-328.



Graph 21: Comparison of Desalination by Prolonged Immersion



Graph 22: Comparison of Desalination by Prolonged Immersion






Table 13: Percent of Salts by Prolonged Immersion in 300 milliliters of water

Tile	Salt	Percent of Total Salts Removed
E-63	NaCl	96.0%
E-39	Na ₂ SO ₄	88.3%
E-52	Gypsum	50.0%
S-16	NaCl	78.6%
S-65	Na ₂ SO ₄	59.1%

6.3 REPEATED WASHINGS

To increase the wash efficiency, the immersion solution was changed after short intervals. The first two experiments with tiles containing sodium chloride show the rate of desalination declines after the first hour (Appendix D Graphs D1-D4). For the tiles containing sodium chloride, 150 milliliters solution was changed every hour five times. The results are reported in Table 14.

Table 14: Percent of Salt Removed During Repeated Washings with 150 milliliters

Tile	Salt		Percent of Total Salt Removed					
		Sol.1	Sol 2	Sol 3	Sol 4	Sol 5	Total %	
E-47	NaCl	49.7%	4.5%	3.2%	2.6%	2.4%	62.4%	
E-51	Na ₂ SO ₄	26.3%	5.6%	4.4%	4.4%	4.4%	45.1%	
E-68	Gypsum	7.7%	2.3%	1.5%	1.5%	1.5%	15.4%	
S-46	NaCl	30.9%	0.90%	0.90%	0.90%	0.90%	34.5%	
S-50	Na ₂ SO ₄	16.7%	1.7%	1.7%	1.7%	1.7%	20.0%	



For the case of tiles with sulfate salts, the rate decrease occurred after two hours (Appendix D Graphs D5-D10). For these tiles the water was changed every two hours. One hundred and fifty milliliters of water and a total of five solutions were used.

The experiment was repeated using a 300ml wash solution, to further verify that increasing the volume of the wash solution has no effect. The results are reported in Table 15. Again, no significant difference was observed between the 150 and 300 milliliter wash solutions, as shown in Graphs 23 and 24.


Table 15: Percent of Salt Removed During Repeated Washings with 300 milliliters

Tile	Salt		Percent of Total Salt Removed					
		Sol.1	Sol 2	Sol 3	Sol 4	Sol 5	Total %	
E-48	NaC1	47.8%	4.2%	4.2%	2.8%	2.5%	61.5%	
E19	Na ₂ SO ₄	33.1%	6.0%	4.8%	4.0%	4.0%	51.9%	
E-67	Gypsum	8.5%	3.1%	3.1%	3.1%	3.1%	20.9%	
S-33	NaCl	27.5%	1.8%	1.3%	1.2%	1.1%	32.9%	
S-42	Na ₂ SO ₄	14.5%	1.6%	1.6%	1.6%	1.6%	19.4%	


The total amount of salts removed remains less than that from the two tests using long term immersion. However, when comparing equal soaking times for both techniques, significantly more salt was removed by repeated washing. This is clearly shown in Graphs 25-29 presented in the next section. The removal of sodium chloride from the earthenware tiles was the most effective when compared to the sulfate salts. This is probably due to the higher mobility of the chloride ion. Again, the correlation between the solubility of the salt and the porosity of the tile remains.



Graph 23: Comparison of Desalination by Repeated Washings



Graph 24: Comparison of Desalination by Repeated Washings





The results confirm that the amount of wash solution has no affect on the efficiency of the desalination of the salts from the ceramic tiles.

To improve the washing efficiency, the tiles were allowed to partially dry between washings. This procedure was successfully applied to in situ washing by nebulization on buildings. The cycle included two steps: 1) washing the tiles in 150ml of deionized water; 2) allowing the tiles to air dry in between soakings. For the tiles treated with sodium chloride, each tile was left in solution for one hour. For the tiles treated with the sulfate salts, each tile was left in the solution for two hours. After the soaking cycle, both the tiles with sodium chloride and with sulfate salts were left to air dry for four hours. This timeframe was chosen because the stoneware tiles lost approximately half of the water weight gained in the immersion cycle during this time.

The results are presented in Table 16 and Graphs 25-29.

Table 16: Percent of Salt Removed During Intermittent Washings


Tile	Salt	Percent of Total Salt Removed				
		Sol.1	Sol 2	Sol 3	Total %	
E-31	NaCl	46.0%	11.5%	7.6%	65.1%	
E-6	Na ₂ SO ₄	50.7%	18.8%	11.8%	81.3%	
E-22	Gypsum	25.0%	25.0%	20.0%	70.0%	
S-3	NaCl	23.7%	5.3%	7.9%	36.9%	
S-20	Na ₂ SO ₄	12.3%	3.8%	5.1%	21.8%	

⁷¹ G. Alessandrini, L.Toniolo, A. Antonioli, A. Di Silvestro, F. Piacenti, S. Righini Ponticelli and L. Formica. "On the Cleaning of Deteriorated Stone Materials," in *Conservation of Stone and Other Materials. Proceedings of the International RILEM UNESCO Congress, Paris, 1993*, ed. Mt.-J.Thiel. (London: E &FN Spon., 1993), p. 503-511.


66



Graph 25: Comparison of Percent of Sodium Chloride Removed from Earthenware Tiles After 3 Hours in Water




Graph 26: Comparison of Percent of Sodium Chloride Removed from Stoneware Tiles After 3 Hours in Water







Graph 27: Comparison of Percent of Sodium Sulfate Removed from Earthenware Tiles After 6 Hours in Water



Graph 28: Comparison of Percent of Sodium Sulfate Removed from Stoneware Tiles After 6 Hours in Water



Graph 29: Comparison of Percent of Gypsum Removed from Earthenware Tiles After 6 Hours in Water



Even with only three cycles, the total amount of salt removed was equal or greater than the total amount of salt removed after five cycles of simple immersion for the same time. When compared to immersion after an equal amount of time, the differences are even larger (Graphs 25-29).

While this technique proves to be the most efficient, the sodium sulfate in the stoneware tile (S20) treated with sodium sulfate began to crystallize on the surface of the tile. When applying this technique in the field, care must be taken to shorten the amount of drying time to prevent this crystallization which will contribute to the deterioration of the object.

6.4 REMOVAL OF SALT MIXTURES

In order to evaluate the desalination of different salts when in combination, the tiles were desalinated by the intermittent washing technique. Both earthenware and stoneware tiles with sodium chloride and sodium sulfate or sodium chloride and gypsum were immersed for one hour in deionized water; since, the majority of the salt contained within the tiles was sodium chloride. Again, the tiles were allowed to air dry four hours in between each washing.

Table 17: Percent of Salt Removed During Intermittent Washings from Earthenware Tiles

Tile	Salt	Percent of Salt Removed				
		Sol.1	Sol 2	Sol 3	Total %	
E-10	NaCl	34.4%	7.0%	6.5%	47.9%	
	Na ₂ SO ₄					
E-26	NaCl	37.5%	7.3%	7.0%	51.8%	
	Na ₂ SO ₄					
E-72	NaCl	40.3%	6.2%	5.2%	51.7%	
	Na ₂ SO ₄					
E-14	NaCl	23.3%	11.5%	9.9%	44.7%	
	Gypsum					
E-30	NaCl	18.6%	7.2%	7.2%	33.0%	
	Gypsum					
E-43	NaCl	25.7%	8.7%	7.8%	42.2%	
	Gypsum					

The results, presented in Tables 17 and 18, again show that desalination of tiles with a higher porosity was more efficient. For these, the average percent of the total salts removed was approximately 48% compared with approximately 23% for the stoneware tiles.

Table 18: Percent of Salt Removed During Intermittent Washings from Stoneware Tiles

Tile	Salt	Percent of Salt Removed					
		Sol.1	Sol 2	Sol 3	Total %		
S-57	NaCl	12.5%	3.7%	4.4%	20.6%		
	Na ₂ SO ₄			_			
S-70	NaCl	11.3%	3.2%	3.8%	18.3%		
	Na ₂ SO ₄						
S-34	NaCl	12.5%	2.9%	2.9%	18.4%		
	Na ₂ SO ₄						
S-45	NaCl	20,3%	3.9%	7.9%	31.6%		
	Gypsum						
S-29	NaCl	16.7%	4.2%	2.8%	23.6%		
	Gypsum						
S-73	NaCl	25.7%	2.7%	2.7%	31.1%		
_	Gypsum						

The amount of each individual salt in the tiles was calculated on the basis of the solubility graphs of the salts considered. The was assumed the same ratio of salts found in

Clifford Price and Peter Brimblecombe, "Preventing Salt Damage in Porous Materials." in *Preventive Conservation, Practice, Theory and Research: Preprints of the Contributions to the Ottawa Congress, 12-16 September 1994* (London: International Institute for Conservation of Historic and Artistic Works, 1994), p. 90-93; and Micahel Steiger and Anke Zeumert, "Crystallization Properties of Salt Mixtures: Comparison of Experimental results and Model Calculations," in *Proceedings of the 8*th

the saturated solutions used for the impregnation remained in the tiles. It was found that the rate of removal was the same for sodium chloride as it was for the sulfate salts.

The equal rate of removal could be observed by comparing the ratio of the amount of sodium chloride to sodium sulfate salt removed with that in the tiles as calculated from the concentration at the eutonic point of the solubility graphs. The ratios are presented in Tables 19 and 20.

For the earthenware tiles, it can be seen that in the case of the tiles containing both sodium chloride and sodium sulfate the ratio remains essentially constant within experimental error, in particular by the third extraction. For the tiles containing sodium chloride and gypsum, the ratios are more erratic because the amount of gypsum measured is near the detection limit of the technique. The values, however, are within the same order of magnitude.

For the case of the stoneware tiles, only the data for the tiles containing sodium chloride and sodium sulfate will be reported (Table 20). Given the small amount of gypsum in these tiles the ratios could not be calculated.



Table 19: Ratio of Amounts of Sodium Chloride to Sulfate Salt Removed From Earthenware Tiles

Tile	Ratio of Salts in the Tiles	Ratio of Salts Removed in First Wash	Ratio of Salts Removed in Second Wash	Ratio of Salts Removed in Third Wash
E10 Sodium Chloride Sodium Sulfate	3.4	3.0	3.3	3.0
E26 Sodium Chloride Sodium Sulfate	3.4	2.2	3.5	3.3
E72 Sodium Chloride Sodium Sulfate	3.4	5.2	5.0	3.0
E43 Sodium Chloride Gypsum	52.6	33.5	44.0	40.0
E14 Sodium Chloride Gypsum	49.6	58.0	28.0	62.5
E30 Sodium Chloride Gypsum	58.0	Sulfate ion concentration below detection limit.	85.0	20.0

For the tiles impregnated with sodium chloride and sodium sulfate, the first washing generally removes a relatively higher amount of sulfate ions, i.e. the chloride to sulfate ratio is smaller than the calculated original ratio. By the third washing, the ratio of sodium chloride was closer to the original ratio.



Table 20: Ratio of Sodium Chloride to Sulfate Salt Removed From Stoneware Tiles

Tile	Ratio of Salts Remaining	Ration of Salts Removed in First Wash	Ratio of Salts Removed in Second Wash	Ratio of Salts Removed in Third Wash
S34 Sodium Chloride Sodium Sulfate	3.4	1.8	3.0	3.0
S57 Sodium Chloride Sodium Sulfate	3.4	2.4	4.0	5.0
S70 Sodium Chloride Sodium Sulfate	3.4	2.2	8.0	12.5

6.5 POULTICE

Aside from total immersion, the most common desalination technique is poulticing. Two different absorbent clays, attapulgite and bentonite were chosen for testing based on their reported high efficiency. The tiles used had already been desalinated by the repeated washing technique. The clay was mixed with washed sand in a ratio of one part clay to two parts sand. This mixture limited the cracking of the poultice as it dried so that good contact between the poultice and the tile was maintained during drying. The mixture also improved the workability of the poultice. Deionized water was added to the mixture until suitable workability was achieved.

_

Lorenzo Lazzarini and Gianni Lombari. "Bentonite for Cleaning and Desalination of Stones," in 9th Triemial Meeting: Dresden, German Democratic Republic, 26-31 August, 1990: Preprints. (Los Angeles: ICOM Committee for Conservation, 1990). p. 336-342; and P. Andrew Lins. "Technical Notes," in Dutch Tiles in the Philadelphia Museum of Art. ed. Jan Daniel van Dam and Pieter Jan Tichelaar (Philadelphia: Philadelphia Museum of Art. 1984).

The tile surface was wetted with a spray of deionized water and placed on a impermeable surface. The poultice was applied to all exposed surfaces of the tile at least one centimeter thick. The tiles were allowed to air dry. After twenty-four hours, the poultice began to crack and detach from the tile. At this time, the poultice was removed from the tile. The poultice containing the salts was dried in an oven at 100 °C until a constant weight was obtained. The dried poultice was then soaked in 150 milliliters of water and left covered for three days. During this time, the solution was occasionally stirred to insure that all the salts went into the solution.

Table 21: Percent of Salt Removed with Poultice

Tile	Salt	Previous Treatment	Poultice	Percent of Salts Removed by Poultice
E48	NaCl	300ml Repeated Washing	Attapulgite	35.5%
E47	NaCl	150ml Repeated Washing	Bentonite	25.4%
E19	Na ₂ SO ₄	300ml Repeated Washing	Attapulgite	16.7%
E51	Na ₂ SO ₄	150ml Repeated Washing	Bentonite	22.7%
S33	NaCl	300ml Repeated Washing	Attapulgite	37.0%
S46	NaCl	150ml Repeated Washing	Bentonite	Experimental Error
S42	Na ₂ SO ₄	300ml Repeated Washing	Attapulgite	18.0%
S50	Na ₂ SO ₄	150ml Repeated Washing	Bentonite	44.0%



The resultant solution was then titrated as previously described. The results in Table 21 show that both of the absorbent clays give adequate desalination results, and no significant difference can be found between the use of bentonite or attapulgite.

6.6 Pressure Poultice

The final desalination technique tested the efficiency of removal by using hydrostatic pressure to flush the salts from a porous material. The tiles containing salt combinations and used during the intermittent washings experimentation were used. Since no significant difference was found between using attapulgite or bentonite, a bentonite poultice was prepared in the same manner discussed above. The top of plastic containers were cut to fit the tiles. The tiles were placed in the holes and the sides were sealed with paraffin wax. The container was filled with 600 milliliters of deionized water, to a height of approximately 4 centimeters, and the lid was sealed. The exposed surface of the tile was wetted with a spray of deionized water, the poultice was placed on the surface one centimeter thick. Finally the entire container was placed on a stand upside down. The rate of water evaporation from the poultice was greater than the rate of water migration through the tile; therefore, the poultice fell off from the tiles before all of the water could migrate through them. When the poultice fell off of the tile, the test was considered complete. All poultices fell off the tiles between nine and sixteen hours after the experiment began. The poultice was then dried and soaked in water as described above. The resulting solutions were then analyzed for salt content.

This technique showed a higher degree of efficiency of desalination than the simple poultice technique.

Table 22: Percent of Salt Removed with Pressure Poultice

Tile	Salt	Previous Treatment	Percent of Salts Removed by Poultice
E10	NaCl Na ₂ SO ₄	Intermittent Washing	58%
E14	NaCl Na ₂ SO ₄	Intermittent Washing	48%
S57	NaCl Na ₂ SO ₄	Intermittent Washing	51%
S45	NaCl Na ₂ SO ₄	Intermittent Washing	100%

The calculated percentages are presented in Table 22. The results also show better removal of sulfate salts than the sodium chloride. This is best illustrated by comparing the ratio of chloride ions to sulfate ions in the tile to that measured in the poultice as shown in Table 23.

Table 23: Ratio of Sodium Chloride to Sulfate Salt Removed with Pressure Poultice

Tile	Ratio of Salts Remaining	Ration of Salts Removed During Poultice
E10 Sodium Chloride Sodium Sulfate	3.3	1.1
S57 Sodium Chloride Sodium Sulfate	3.5	0.96

Only the values for the sodium chloride sodium sulfate mixtures are presented.



7. CONCLUSION

This study has served to evaluate the efficiency of various desalination methods from samples with known amounts of salt. Two sets of tiles with different porosities and impregnated with single salts and their mixtures were used. The salts chosen sodium chloride, sodium sulfate, and gypsum, alone or in their mixtures, are the most frequently found in both historic buildings and archaeological ceramics. The results obtained can be summarized as follows.

The removal efficiency does not appear to be affected by the amount of salts present originally in the material. In objects containing a single salt, the most soluble salts are the easiest to remove. In general, salts in mixtures are removed in the same ratio as they are present in the object.

The amount of water used for immersion does not influence the efficiency of salt removal. While long term immersion appears to remove virtually all the salts, the length of immersion time is not practical and may be damaging to the object.

Repeated washing does increase the efficiency of desalination, but the first washing always proves to be the most effective. Allowing objects to partially dry in between successive washings doubles the removal efficiency in subsequent immersions. Although this was proven for objects, the principle is applicable for in situ washing of buildings.⁷⁴

⁷⁴ G. Alessandrini, L.Toniolo, A. Antonioli, A. Di Silvestro, F. Piacenti, S. Righini Ponticelli and L. Formica, "On the Cleaning of Deteriorated Stone Materials," in *Conservation of Stone and Other*

As expected, the removal of salts from more porous materials is easier. However, salts such as mirabalite, sodium sulfate decahydrate, appear to concentrate in larger pores and hence were more effectively removed from the stoneware tiles during the first washing. Further studies are needed to elucidate the effect of pore size and shape on the accumulation of salt during crystallization. This may also influence the rate of removal of one salt preferentially to another.

Poulticing appears to be even more effective than one hour total immersion.

Poulticing has also proven to be a more effective salt removal method for stoneware tiles than for earthenware tiles. Pressure poulticing significantly increases the efficiency of desalination.

Apart from evaluating the effectiveness of salt removal by various methods and their variations, this study may well serve as a guideline for estimating the amounts of salt remaining in a material, after one of these procedures is applied. Knowing the approximate efficiency of the technique and measuring the amount of salt removed from materials of similar porosity, the original salt content of the material can be estimated. This is an important contribution to the field of conservation. Since, as mentioned previously, no simple, accurate, and nondestructive method to determine salt content within porous materials exists.

Materials, Proceedings of the International RILEM UNESCO Congress, Paris, 1993. ed. M.-J.Thiel, (London: E &FN Spon., 1993), p. 503-511.



APPENDIX A: SOLUBILITY OF COMMON SALTS FOUND IN BUILDINGS⁷⁵

Chemical Formula	Name	Solubility g/100ml in cold water or (°C)	Molarity
CaSO ₄ •2H ₂ O	Gypsum	0.241	0.014 M
Na ₂ SO ₄	Thenardite	4.76 (0°C)	0.34 M
Na ₂ SO ₄ •10H ₂ O	Mirabilite	11 (0°C)	0.34 M
K ₂ SO ₄	Arcanite	12 (25°C)	0.69 M
MgSO ₄ •7H ₂ O	Epsomite	71 (20°C)	2.9 M
CaCl		74.5 (20°C)	6.7 M
NaCl	Halite	35.7(0°C)	6.1 M
KCI	Sylvite	34.7 (30? °C)	4.7 M
MgCl ₂		54.25 (20? °C)	5.7 M
KNO ₃	Saltpeter	13.3 (0°C)	1.3 M
NaNO ₃	Soda Niter	92.1 (25°C)	10.8 M
CaHPO₄•2H₂O	Brushite	0.0316 (28? °C)	0.0018 M
3MgCO ₃ •Mg(OH) ₂ •3H ₂ O	Hydromagnesite	0.04	0.0011 M
Na ₂ CO ₃		7.1 (0°C)	0.67 M
Na ₂ CO ₃ •H ₂ O	Thermonatrite	33	2.7 M
Na ₂ CO ₃ •10H ₂ O	Natron/Soda	21.52 (0°C)	0.72 M
CaCO ₃	Calcite	0.0014(25°C)	1.4 x 10-4 M
Na ₂ CO ₃ •NaHCO ₃ •2H ₂ 0	Trona	13 (0°C)	0.58 M

_

¹⁵ Robert C. Weast (ed.), "Physical Constants of Inorganic Compounds," *CRC Handbook of Chemistry and Physics* 58th Edition. (Cleveland: CRC Press, 1978), p. B-83-B178.

APPENDIX B: PORE MEASUREMENTS OF EARTHENWARE TILE


Pore	Major Axis mm	Minor Axis mm	Area mm ²
	0.15	0.10	0.0491
2	0.17	0.10	0.0556
3	0.22	0.07	0.0504
4	0.08	0.05	0.0131
5	0.08	0.01	0.0026
6	0.03	0.02	0.0020
7	0.03	0.02	0.0020
8	0.03	0.02	0.0020
9	0.02	0.02	0.0013
10	0.03	0.01	0.0010
11	0.01	0.01	0.0003
12	0.02	0.01	0.0007
13	0.01	0.01	0.0003
14	0.01	0.01	0.0003
15	0.01	0.01	0.0003
16	0.09	0.02	0.0059
17	0.06	0.04	0.0079
18	0.03	0.02	0.0020
19	0.01	0.01	0.0003
20	0.06	0.04	0.0079
21	0.02	0.01	0.0007
22	0.03	0.02	0.0020
23	0.02	0.02	0.0013
24	0.01	0.01	0.0003
25	0.01	0.01	0.0003
26	0.01	0.01	0.0003
27	0.02	0.01	0.0007
28	0.01	0.01	0.0001
29	0.01	0.01	0.0001
30	0.01	0.01	0.0003
Mean	0.044	0.024	0.0033
Median	0.02	0.01	0.0007
Standard Deviation	0.054	0.026	0.015

APPENDIX C: PORE MEASUREMENTS OF STONEWARE TILE


Pore	Major Axis mm	Minor Axis mm	Area mm ²
1	0.71	0.51	1.14
2	0.17	0.10	0.06
3	0.05	0.05	0.01
+	0.43	0.18	0.25
5	0.05	0.05	0.01
6	0.06	0.06	0.01
7	0.13	0.02	0.01
8	0.10	0.02	0.01
9	0.05	0.03	0.00
10	0.05	0.03	0.00
11	0.07	0.03	0.01
12	0.12	0.02	0.01
13	0.06	0.04	0.01
14	2.40	0.80	6.03
15	0.48	0.20	0.30
16	2.72	0.64	5.47
17	0.12	0.12	0.05
18	0.12	0.08	0.03
19	0.12	0.08	0.03
20	0.16	0.04	0.02
21	0.08	0.08	0.02
22	0.16	0.12	0.06
23	0.16	0.08	0.04
24	0.12	0.08	0.03
25	0.04	0.04	0.01
26	0.04	0.04	0.01
27	0.04	0.04	0.01
28	0.04	0.02	0.00
29	0.02	0.02	0.00
30	0.04	0.04	0.01
Mean	0.30	0.12	0.11
Median	0.11	0.05	0.02
Standard Deviation	0.63	0.19	1.46

APPENDIX D: ADDITIONAL DESALINATION GRAPHS AND TABLES


Graph D1: Grams of Sodium Chloride Removed During 150ml Prolonged Immersion of Earthenware Tile




Graph D2: Grams of Sodium Chloride Removed During 300ml Prolonged Immersion of Earthenware Tile




Graph D3: Grams of Sodium Chloride Removed During 150ml Prolonged Immersion of Stoneware Tile




Graph D4: Grams of Sodium Chloride Removed During 300ml Prolonged Immersion of Stoneware Tile




Graph D5: Grams of Sodium Sulfate Removed During 150ml Prolonged Immersion of Earthenware Tile




Graph D6: Grams of Sodium Sulfate Removed During 300ml Prolonged Immersion of Earthenware Tile




Graph D7: Grams of Sodium Sulfate Removed During 150ml Prolonged Immersion of Stoneware Tile



Graph D8: Grams of Sodium Sulfate Removed During 300ml Prolonged Immersion of Stoneware Tile



Graph D9: Grams of Gypsum Removed During 150ml Prolonged Immersion of Earthenware Tile



Graph D10: Grams of Gypsum Removed During 300ml Prolonged Immersion of Earthenware Tile






Table D1: Grams of Salt Removed During Intermittent Washings of Earthenware Tiles

Tile	Salt	Calculated	Gram	s of Salt Ren	noved
		Amount of Salts (grams)	Sol. l (grams)	Sol 2 (grams)	Sol 3 (grams)
E-10	Total	3.72	1.28	0.26	0.24
	NaCl	2.87	0.96	0.20	0.18
	Na ₂ SO ₄	0.85	0.32	0.06	0.06
E-26	Total	3.71	1.39	0.27	0.26
	NaCl	2.86	0.96	0.21	0.20
	Na ₂ SO ₄	0.85	0.43	0.06	0.06
E-72	Total	3.87	1.56	0.24	0.20
	NaCl	2.98	1.31	0.20	0.15
	Na ₂ SO ₄	0.89	0.25	0.04	0.05
E-43	Total	2.68	0.69	0.23	0.21
	NaCl	2.63	0.67	0.22	0.20
	Gypsum	0.05	0.02	0.005	0.005
E-14	Total	2.53	0.59	0.29	0.25
	NaCl	2.48	0.58	0.28	0.25
	Gypsum	0.05	0.01	0.01	0.004
E-30	Total	2.36	0.44	0.17	0.17
	NaCl	2.32	0.44	0.17	0.16
	Gypsum	0.04	< 0.002	0.002	0.008

Table D2: Grams of Salt Removed During Intermittent Washings of Stoneware Tiles

Tile	Salt	Calculated	Gran	ns of Salt Ren	noved
		Amount of Salts (grams)	Sol.1	Sol 2	Sol 3
S-34	Total	1.36	0.17	0.04	0.04
	NaCl	1.05	0.11	0.03	0.03
	Na ₂ SO ₄	0.31	0.06	0.01	0.01
S-57	Total	1.36	0.17	0.05	0.06
	NaC1	1.05	0.12	0.04	0.05
	Na ₂ SO ₄	0.31	0.05	0.01	0.01
S-70	Total	1.41	0.16	0.05	0.05
	NaCl	1.09	0.11	0.04	0.05
	Na ₂ SO ₄	0.32	0.05	0.005	0.004
S-73	Total	0.74	0.19	0.02	0.02
	NaCl	0.73	0.18	0.02	0.02
	Gypsum	0.01	0.008	< 0.0002	0.002
S-45	Total	0.76	0.154	0.03	0.06
	NaCl	0.75	0.15	0.01	0.06
	Gypsum	0.01	0.004	0.02	0.00
S-29	Total	0.72	0.12	0.03	0.02
	NaCl	0.71	0.11	0.03	0.02
	Gypsum	0.01	0.008	<0.0002	< 0.0002



Table D3: Grams of Salt Removed with Pressure Poultice

Tile	Salt	Estimated Grams of Salt Remaining in Tile	Grams of Salts Removed by Poultice
E10	Total	1.94	1.13
	NaCl	1.53	0.58
	Na ₂ SO ₄	0.46	0.55
E14	Total	1.39	0.67
	NaCl	1.37	0.50
	Gypsum	Not Detectable	Not Detectable
S57	Total	1.08	0.55
	NaCl	0.83	0.27
	Na ₂ SO ₄	0.24	0.28
S45	Total	0.51	0.52
	NaC1	0.53	0.30
	Gypsum	Not Detectable	Not Detectable

BIBLIOGRAPHY

- Adams. Ralph N. et al. Treatise on Analytical Chemistry Part I Theory and Practice Volume 4 Section D-2 Electrical Methods of Analysis Chapter 42-52. Easton, PA: John Wiley & Sons, 1963.
- Aires-Barros, L. and A. Mauricio. "Chronology, Probability Estimations and Salt Efflorescence Occurrences Forecasts on Monumental Building Stones Surfaces." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 497-511. Berlin: Moller Druck und Verlag, 1996.
- Alessandrini, G., L.Toniolo, A. Antonioli, A. Di Silvestro, F. Piacenti, S. Righini Ponticelli and L. Formica. "On the Cleaning of Deteriorated Stone Materials." In *Conservation of Stone and Other Materials. Proceedings of the International RILEM UNESCO Congress, Paris, 1993*, edited by M. J. Thiel, p. 503-511. London: E &FN Spon, 1993.
- Alonson, Francisco, Javier and Rosa Maria Esbert. "Saline Spray Action on a Treated Dolomitic Stone." In *Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994*, edited by Vasco Fassina et al., p. 867-870. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Antunes, J. L. "Characterization of Portuguese 17th Century Tiles." In *Proceedings of the International Symposium on Ceramics in Architecture of the 8th CIMTEC-World Ceramics Congress and Forum on New Materials Florence, Italy June 28-July1, 1984, edited by P. Vincenzini, p.653-660. Faenza: L Techna, 1995.*
- Arnold, A. "Behavior of Some Soluble Salts in Stone Deterioration." In 2nd
 International Symposium on the Deterioration of Building Stones From 27th
 September to 1st October 1976, Athens, Greece, p. 27-36. Athens: 2nd International Symposium on the Deterioration of Building Stones, 1976.
- Arnold, A. "Determination of Mineral Salts from Monuments." *Studies in Conservation*. Vol. 29 (1984) p. 129-138.
- Arnold, A. and K. Zehnder. "Decay of Stony Materials by Salts on Humid Atmosphere." In 17th International Congress on Deterioration and Conservation of Stone Torun 12-14 September 1988, p. 138-148. Torun: Nicholas Copernicus University Press Department, 1988.
- Arnold, A. and A. Kueng. "Crystallization and Habits of Salt Efflorescence on Walls I Methods of Investigation and habits." In *11th International Congress on*



- Deterioration and Conservation of Stone, Lansanne 25-27 September 1985, edited by G. Félix, p. 255-267. Lausanne: Presses Polytechniques Romandes, 1985.
- Arnold, A. and K. Zehnder. "Crystallization and Habits of Salt Efflorescence on Walls II Conditions of Crystallization." In *Vth International Congress on Deterioration and Conservation of Stone*, *Lausanne 25-27 September 1985*, edited by G. Félix, p. 269-277. Lausanne: Presses Polytechniques Romandes, 1985.
- Arnold, Andreas and Konrad Zehnder. "Salt Weathering on Monuments." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st <i>International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 31-58. Brescia, Italy: Grafo, 1990.
- Arnold, Andreas. "Nature and Reactions of Saline Minerals in Walls." In *The Conservation of Stone II Preprints of the Contributions to the International Symposium, Bologna, 27-30 October 1981 Part A Deterioration,* edited by Raffaella Rossi-Manaresi, p. 13-23. Bologna: Centro Per La Conservazione Delle Sculture All'Aperto, 1981.
- Arnold, Andreas. "Rising Damp and Saline Minerals." In Fourth International Congress on the Deterioration and Preservation of Stone Objects July 7-9, 1982 Proceedings, edited by K. L. Gauir and J. A. Gwinn, p. 11-28. Louisville: University of Louisville. 1982.
- Arnold, Andreas. "Soluble Salts and Stone Weathering." In *The Conservation of Stone I Proceedings of the International Symposium Bologna, June 19-21, 1975*, edited R. Rossi-Manaresi, p. 133-135. Bologna: Centro Per La Conservazione Delle Sculture All'Aperto, 1976.
- Auger, Fernand. "World Limestone Decay under Marine Spray and Conditions." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 65-69. Brescia, Italy: Grafo, 1990.
- Balen, K. Van, L. Binda, R. Van Hees, and L. Franke. "Damage to Historic Brick Masonry Structures Masonry Damage Diagnostic Atlas for Evaluation of Deterioration." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1687-1691. Berlin: Moller Druck und Verlag, 1996.
- Baronio, G., L. Binda, and A. E. Charola. "Deterioration of Bricks with and without Perforations Due to Salt Crystallization." In *Proceedings of the 7th International Brick Conference Melbourne Australia 17-20 February 1985*, edited by Tom McNeilly and John C. Scrivener, p. 223-232. Melbourne: University of Melbourne, 1985.



- Begonha, A., M. A. Sequeira Braga, and F. Gomes da Silva. "Rainwater as a Source of the Soluble Salts Responsible for Stone Decay in the Granitic Monuments of Oporto and Braga-Portugal." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 481-487. Berlin: Moller Druck und Verlag, 1996.
- Bennett, A. Lee. "The Use of Overglazes for Polychrome Terra Cotta." *Journal of the American Ceramics Society*, Vol. 9, No. 4 (April 1926), p. 185-188.
- Berry, Janet and Clifford A. Price. "The Movement of Salts in Consolidated Stone." In Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994, edited by Vasco Fassina et al., p.845-848. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Binda, L. and Baronio G. "Mechanisms of Masonry Decay Due to Salt Crystallization." Durability of Building Materials 4, (1987) p. 227-240.
- Binda, L., G. Baronio, and A. E. Charola. "Deterioration of Porous Materials Due to Salt Crystallization Under Different Thermohygrometric Conditions. I. Brick." In Vth International Congress on Deterioration and Conservation of Stone, Lansanne 25-27 September 1985, edited by G. Félix, p. 279-288. Lausanne: Presses Polytechniques Romandes, 1985.
- Bläuer Böhm, Christine. "Assessment of Quantitative Salt Analysis by the Water Extraction Method on Lime Mortars." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1505-1519. Berlin: Moller Druck und Verlag, 1996.
- Bowley, M. J. "Desalination of Stone: A Case Study." In *Masonry Conservation and Cleaning Handbook*, edited by Keith Blades et al., p. 154-163. Ottawa: Association For Preservation Technology, 1985.
- Brownell, Wayne E. "Efflorescence Resulting from Sulfates in Clay Raw Materials." Journal of the American Ceramic Society Vol. 41 No. 8 (1958), p. 310-314.
- Buil, Michel. "Thermodynamic and Experimental Study of the Crystallization Pressure of Water-Soluble Salts." In *Materials Science and Restoration Proceedings of the International Conference September 6-8, 1983*, edited by F. H. Whittmann, p.373-377. Lausanne: Technische Akademie Esslingen, 1983.
- Caner, E. N. S. Demirci, and A. G. Turkmenoglu. "Deterioration of Dolomite by Soluble Salts in Divrigi Great Mosque-Turkey." In *Vth International Congress on Deterioration and Conservation of Stone, Lansanne 25-27 September 1985*, edited by G. Félix, p. 299-305. Lausanne: Presses Polytechniques Romandes, 1985.

- Caner-Saltik, E. N., I. Schumann, and L Franke. "Stages of Damage in the Structure of Brick Due to Salt Crystallization." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 47-58. London: Donhead Publishing Ltd., 1998.
- Cereceda, Miguel Luis, et al. "Characteristics, Forms and Mechanism of Weathering of the Stone Caused by the Salt Spray in the Stone Used in the Main Monuments in the City of Alicante (Spain)." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, ecited by Fulvio Zezza, p. 91-96. Brescia, Italy: Grafo, 1990.
- Charola, A. E. and R. J. Koestler. "The Action of Salt-Water Solutions in the Deterioration of the Silicio-Aluminate Matrix of Bricks." In *Il Mattone di Venezia : Contributi Presentati al Concorso di Idee su Patologia, Diagnosi e Terapia del Mattone di Venezia : Ateneo Veneto, Venezia, 29 Ottobre 1982*, p. 67-76. Venezia: Comune di Venezia, 1982.
- Charola, A. Elena, and Sara Nunberg. "Soluble Salts in Ceramic Bodies: Deterioration Due to Minimal Changes in Relative Humidity." Manuscript to be submitted to *Studies in Conservation*.
- Charola, A. E. and S. Z. Lewin. "Examples of Stone Decay Due to Salt Efflorescence." In *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-27 10 1979*, p. 153-163. Padova: Universita degli Studi di Padova, 1979.
- Charola, A. Elena and Johannes Weber. "The Hydration-Dehydration Mechanism of Sodium Sulphate." In *Proceedings of the 7th International Congress on Deterioration and Conservation of Stone, Lisbon, Portugal 15-18 June, 1992*, edited by J. Delgado Rodrigues, p. 581-590. Lisbon: Laboratorio Nacional de Engenharia Civil, 1992
- Charola, A. Elena, Johannes Weber, and Erica Bolle. "Preliminary Studies of Deterioration Patterns at Cerro Colorado, Argentina: Open Cave Formation and Honeycomb Weathering." In 9th Triennial Meeting: Dresden, German Democratic Republic, 26-31 August, 1990: Preprints, p. 521-525. Los Angeles: ICOM Committee for Conservation, 1990.
- Chatterji, S., P. Christensen, and G. Overgaard. "Mechanisms of Breakdown of Natural Stones Caused by Sodium Salts." In *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-27 10 1979*, p. 131-134. Padova: Universita degli Studi di Padova, 1979.
- Ciabach, J. and Slawomir Skibinski. "Analyses of the Total Salt Content and Control of Salt Removal from Stone Historical Objects." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on*

- *Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 325-328. Brescia, Italy: Grafo, 1990.
- "Cleaning Brick Masonry." *BIA Technical Notes on Brick Construction*, Vol. 20 Revised. (Sept/Oct 1977).
- Creahan, Julie. "Controlling Relative Humidity and Saturated Calcium Nitrate Solutions." *WAAC Newsletter* Vol. 13, No. 1 (January 1991), p. 17-18.
- Crevecoeur, R. "The Desalination of a Marble Carved Seat in the Royal Palace, Amsterdam." In *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-27.10 1979*, p. 471-479. Padova: Universita degli Studi di Padova, 1979.
- Crèvecoeur, R. and H. H. O. Jahn. "The Preservation of Venetian Brickwork by the Use of a Salt Resistant and Vapour Permiable Plaster." In *Il Mattone di Venezia : Contributi Presentati al Concorso di Idee su Patologia, Diagnosi e Terapia del Mattone di Venezia : Ateneo Veneto, Venezia, 29 Ottobre 1982*, p. 67-76. Venezia: Comune di Venezia, 1982.
- Davison, J. I. "A Study of Efflorescence in Clay Bricks." *The Journal of the Canadian Ceramic Society*, Vol. 35 (1966), p. 85-92.
- De Vecchi, Gp., L. Lazzarini, Vitturi L. Menegazzo. "Deterioration Due to Salt Efflorescence on Interior Marble Facings of the Church of S. Maria Dei Miracoli, Venice." In *The Conservation of Stone II Preprints of the Contributions to the International Symposum, Bologna, 27-30 October 1981 Part A Deterioration*, edited by Raffaella Rossi-Manaresi, p. 417-441. Bologna: Centro Per La Conservazione Delle Sculture All'Aperto, 1981.
- Dingethal, G., P. Andriolo-Stagno and H.Weber "Patologia e Cura Dimurature in Mattoni Danneggiate Dall'Umidita' e Dalla Presenza di Sali" In *Il Mattone di Venezia : Contribnti Presentati al Concorso di Idee sn Patologia, Diagnosi e Terapia del Mattone di Venezia : Ateneo Veneto, Venezia, 29 Ottobre 1982*, p. 397-435. Venezia: Comune di Venezia, 1982.
- Doehne, Eric. "In Situ Dynamic of Sodium Sulfate Hydration and Dehydration in Stone Pores: Observation at High Magnification Using th Environmental Scanning Electron Microscope." In Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994, edited by Vasco Fassina et al., p. 143-150. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Domaslowski, Wieslaw and Alina Tomaszewska-Szewczyk. "Desalting of Stones by Means of Ion Exchangers." In *Proceedings of the 8th International Congress on*

- Deterioration and Conservation of Stone, 30 September 4 October 1996, edited by Joseph Riederer, p. 1371-1381. Berlin: Moller Druck und Verlag, 1996.
- Duttlinger, Werner, and D. Knofel. "Chemical and Mineralogical Investigations of Decay Phenomena at the Curbs of the Wells in Bad Naubeim." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 71-74. Brescia, Italy: Grafo, 1990.
- Efes, Y. "Investigations on Correlations Between the Porosity and the Corrosion of Natural Stones." In *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-27-10 1979*, p. 231-243. Padova: Universita degli Studi di Padova, 1979.
- Fassina, V. "Marine Spray and Polluted Atmospheres as Factors to Monument in the Mediterranean Coastal Environment: An Analytical Study of Some Samples from the Sanctuary of Demeter in Eleusis (Athens)." In *Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994*, edited by Vasco Fassina et al., p. 287-294. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Fassina, V., R. Arbizzani, A. Naccari, and M. Favaro. "Brick Masonry of the Crypt of San Marco Basilica." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 407-426. London: Donhead Publishing Ltd., 1998.
- Fassina, Vasco, Rossana Arbizzani, and Andrea Naccari. "Salt Efflorescence on the Marble Slabs of S. Maria Del Miracoli Church: A Survey on Their Origin and on the Methodology of Their Removal." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 523-534. Berlin: Moller Druck und Verlag, 1996.
- Fidler, John. "Fragile Remains: An International Review of Conservation Problems in the Decay and Treatment of Architectural Terracotta and Faience." In *Architectural Ceramics Their History, Manufacture and Conservation A Joint Symposium of English Heritage and the United Kingdom Institute for Conservation 22-25 September 1994*, p. 7-25. London: James, 1996.
- Fifield, F. W. and D. Kealey. *Principles and Practice of Analytical Chemistry 2nd Edition*. London: International Textbook Company Limited, 1983.
- Fink, Colin G. "Incrustations on Porous Pottery: A New Method of Cleaning without Loss of Pigment." *Technical Studies* Vol. 2 (1933-4): p. 59-61.

- Franke, L. and 1 Schumann. "Causes and Mechanisms of the Decay of Historic Brick Buildings in Northern Germany." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 25-34. London: Donhead Publishing Ltd., 1998.
- Franke, L. and I Schumann. "Indoor Brick Damage Investigation of the Roles of Pore Size and Salts." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 35-46. London: Donhead Publishing Ltd., 1998.
- Franke, L. and J. Grabau. "Transport of Salt Solutions in Brickwork." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 167-172. London: Donhead Publishing Ltd., 1998.
- Franke, L., and J. Grabau. "Influence of Salt Content on the Drying Behavior of Brick." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 59-68. London: Donhead Publishing Ltd., 1998.
- Friese, P., and A. Protz. "Desalination of Brickwork and Other Porous Media." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 335-345. London: Donhead Publishing Ltd., 1998.
- Fritsch, H. and E. Schamberg. "The Influence of Salts on the Impregnation of Natural Stone Materials." In *VIth International Congress on Deterioration and Conservation of Stone Torun 12-14 September 1988*, p. 171-181. Torun: Nicholas Copernicus -University Press Department, 1988.
- Gabriel, G. and R. J. Inkpen. "The Nature of Decay of Monk's Park Limestone Under Simulated Salt Weathering." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 573-578. Berlin: Moller Druck und Verlag, 1996.
- Gaitan, Espinosa, Jesus and Rosario Villedas Sanchez. "Characterization of the Bricks Used in the Construction of the Alcazaba (Malaga, Spain)." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1679-1677. Berlin: Moller Druck und Verlag, 1996.
- Galli, G., M. Matteini, A. Moles, and C. Manganelli. "Intervento di Desalinazione del Dossale di G. Di Rigino di Verona." In *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-2710 1979*, p. 491-499. Padova: Universita degli Studi di Padova. 1979.

- Gedye, Ione. "Pottery and Glass." In *The Conservation of Cultural Property with Special Reference to Tropical Conditions, p. 109-113*. Paris: UNESCO, 1968.
- Hees, R. P. J. van. "Damage Caused by Salts to Curacao-Monuments." In Structural Repair and Maintenance of Historical Buildings II Proceedings of the Second International Conference Held in Seville, Spain 14-16 May 1991, edited by C. A. Brebbia et al., p.141-155. Boston, Computational Mechanics Publications, 1991.
- Heiman, J. L. "Rising Damp and Salt Attack in Old Masonry." In *Proceedings of the 7th International Brick Conference Melbourne Australia 17-20 February 1985*, edited by Tom McNeilly and John C. Scrivener, p. 233-244. Melbourne: University of Melbourne, 1985.
- Helmi, Fatma M. "Study of Salt Problem in the Sphinx, Giza, Egypt." In 9th Triennial Meeting: Dresden, German Democratic Republic, 26-31 August, 1990: Preprints, p. 326-335. Los Angeles: ICOM Committee for Conservation, 1990.
- Herppich, S. "Bricks Under the Influence of Huge Salt Immissions Building of a Thuringian Potash Mine." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p.477-484. London: Donhead Publishing Ltd., 1998.
- Hewat, James M. "Approaches to the Conservation of Salt Deteriorated Brick." Master of Science Thesis, Philadelphia: University of Pennsylvania, 1996.
- Hibbert, D. B. and A. M. James. *Dictionary of Electrochemistry Second Edition*. New York: John Wiley & Sons, 1984.
- Hodges, Henry W. M. "The Conservation Treatment of Ceramics in the Field." In In Situ Archaeological Conservation: Proceedings of Meetings April 6-13, 1986 Mexico, 1987, p. 144-9. Los Angeles: Getty Conservation Institute, 1986.
- Jedrzejewska, Hanna. "Removal of Soluble Salts from Stone." In *Preprints of the Contributions to the New York Conference on Conservation of Stone and Wooden Objects, 7-13 June 1970 Vol. 1*, p. 19-34. London: International Institute for Conservation of Historic and Artistic Works, 1971.
- Jeffery, G. H., J. Bassett, J. Mendham, and R. C. Denney. *Vogel's Textbook of Quantitative Chemical Analysis Fifth Edition*. New York: Longman Scientific and Technical, 1989.
- Johnson, James R. "Guide to Soluble Salts Field Testing." *Materials Performance* Vol. 36, No. 8, (1997); p. 27-30.
- Klemm, W., and H. Siedel. "Sources of Sulfate Salt Efflorescence at Historical Monuments A Geochemical Study from Freiberg, Saxony." In *Proceedings of the*

- 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996, edited by Joseph Riederer, p. 489-495. Berlin: Moller Druck und Verlag, 1996.
- Koob, Stephen B. "The Use of Acryloid B-72 in the Treatment of Archaeological Ceramics: Minimal Intervention." In *Materials Issues in Art and Archaeology II Symposium Held April 17-21, 1990 San Francisco*, edited by Pamela B. Vandiver et al., p. 591-596. Pittsburgh: Materials Research Society: 1991.
- Kumar, Rakesh and Clifford A. Price. "The Influence of Salts on the Hydrolysis and Condensation of Methyl-Trimethoxysilane." In *Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994*, edited by Vasco Fassina et al., p. 861-865. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
 - Larney, J. "Ceramic Restoration in the Victoria and Albert Museum." *Studies in Conservation* Vol. 16 (1971): p. 69-82.
 - Laue, Steffen, Christine Bläuer Böhm, and Daniel Jeannette. "Saltweathering and Porosity Examples from the Crypt of St. Maria im Kapitol, Cologne." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 513-522. Berlin: Moller Druck und Verlag, 1996.
 - Lazzarini, Lorenzo and Gianni Lombari. "Bentonite for Cleaning and Desalination of Stones." In 9th Triemial Meeting: Dresden, German Democratic Republic, 26-31 August, 1990: Preprints, p. 336-342. Los Angeles: ICOM Committee for Conservation, 1990.
 - Lees, T. P. "Deterioration Mechanisms." In *Durability of Concrete Structures: Investigation, Repair, Protection*, p. 10-36. New York: E & F. N. Spon, 1992.
 - Lehmann, Janusz. "Damage by Accumulation of Soluble Salts in Stonework." In *Preprints of the Contributions to the New York Conference on Conservation of Stone and Wooden Objects, 7-13 June 1970 Vol. 1*, p. 35-46. London: International Institute for Conservation of Historic and Artistic Works, 1971.
 - Lewin, Seymour. "The Mechanism of Masonry Decay Through Crystallization." In *Conservation of Historic Stone Buildings and Momments.* Washington, D. C.: National Academy Press, 1982.
 - Lewin, Seymour. "The Susceptibility of Calcareous Stones to Salt Decay." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st <i>International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 59-63. Brescia, Italy: Grafo, 1990.

- Ling, Denise, and Sandra Smith. "To Desalinate or not to Desalinate? That is the Question. In *Le Dessalement des Materiaux Poreux 7es Journees D'Etudes de La SFIIC Poitiers*, 9-10 Mai 1996, p. 65-74. Champs-sur-Marne: SFIIC, 1996.
- Lins, P Andrew. "Technical Notes" In *Dutch Tiles in the Philadelphia Museum of Art*, edited by Jan Daniel van Dam and Pieter Jan Tichelaar. Philadelphia: Philadelphia Museum of Art, 1984.
- Livingston, Richard A., and Thomas H. Taylor Jr. "Diagnosis of Salt Damage at a Smokehouse in Colonial Williamsburg." *APT Bulletin* Vol. XXIII No. 3 (1991): p. 3-12.
- Livingston, Richard, Stephen Fitz, and Norbert S., Baer. "The NATO-CCMS Pilot Study on the Conservation of Brick Monuments." In *Fifth North American Masonry Conference*, *University of Illinois at Urbana-Champaign June 3-6, 1990*, p. 805-812. Boulder: Masonry Society, 1990.
- Llopis, V. Galvan, A. Mas Tomas, and E. Gil Benso. "Conditions that Influence the Position and Crystallization of Salts." In *Proceedings of the 7th International Congress on Deterioration and Conservation of Stone, Lisbon, Portugal 15-18 June, 1992*, edited by J. Delgado Rodrigues, p. 895-903. Lisbon: Laboratorio Nacional de Engenharia Civil, 1992
- Lopez-Acevedo, V. C. Viedma, V. Gonzalez, and A. La Iglesia. "Salt Crystallization in Porous Construction Materials II. Mass Transport and Crystallization Processes." *Journal of Crystal Growth* Vol. 182 (1997), p. 103-110.
- Manaresi, Raffaella, and Antonella Tucci. "Pore Structure and Salt Crystallization: "Salt Decay" of Agrigento Biocalcarenite and "Case Hardening" in Sandstone." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 97-100. Brescia, Italy: Grafo, 1990.
- Martin, Lourdes, Miguel Angel Bello, and Antonio Martin. "The Efflorescences of the Cathedral of Almeria (Spain)." In *Proceedings of the 7th International Congress on Deterioration and Conservation of Stone, Lisbon, Portugal 15-18 June, 1992*, edited by J. Delgado Rodrigues, p. 869-871. Lisbon: Laboratorio Nacional de Engenharia Civil, 1992.
- Massari, Giovanni and Ippolito. *Damp Buildings Old and New*, translated by Cynthia Rockwell. Rome: ICCROM, 1993.
- McCrone, Walter C. and John Gustav Delly. *The Particle Atlas Electronic Edition*. Chicago: McCrone Research Institute, 1992.

- McMahon, David J., Paul Sandberg, Kevin Folliard, and P. K. Mehta. "Deterioration Mechanisms of Sodium Sulfate." In *Deterioration and Preservation of Stones 3rd International Congress Venezia 24-27* 10 1979, p. 705-714. Padova: Universita degli Studi di Padova, 1979.
- Moropoulou, A. et al. "Marine Spray and Polluted Atmospheres as Factors of Damage to Monuments in the Mediterranean Coastal Environment a Preliminary Approach to the Case of Demeter Sanctuary in Eleusus." In *Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994*, edited by Vasco Fassina et al., p. 275-285. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Moropoulou, Antonio and Panagiotis Theoulakis. "Conditions Causing Destructive NaCl Crystallization into the Porous Sandstone, Building Material of the Medieval City of Rhodes." In *The Conservation of Monuments in the Mediterranean Basin Proceedings of the 2nd International Symposium Geneva, 19-21 November 1991*, edited by Daneielle Decrouez et al., p. 493-499. Geneva: Museum d'Histoire Naturelle and Musee d'Art et d'Histoire, 1991.
- O'Brien, Patrick. "An Experimental Study of the Effects of Salt Erosion on Pottery." *Journal of Archaeological Science* Vol. 17 (1990): p. 393-401.
- Olive, J. and C. Pearson. "The Conservation of Ceramics from Marine Archaeological Sources." In *Preprints of the Contributions to the Stockholm Congress 2- 6 June 1975 Conservation in Archaeology and the Applied Arts*, p. 63-68. London: International Institute for Conservation, 1975.
- Paloma, A., F. Puertas, and M. T. Blanco. "Mortars for Restoration Decay Due to Salt Crystallization." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1547-1555. Berlin: Moller Druck und Verlag, 1996.
- Parkinson, A. Eric. "The Preservation of Cuneiform Tablets by Heating to a High Temperature." *Museum News* (March 1, 1950): p. 6-8.
- Paterakis, A. B. "The Deterioration of Ceramics by Soluble Salts and Methods for Monitoring Their Removal." In *Recent Advances in the Conservation and Analysis of Artifacts*, p. 67-73. London: Institute of Archaeology, 1987.
- Paterakis, Alice Boccia and Sarah Nunberg. "The Stabilization of Archaeological Pottery in an Excavation Study Collection through Relative Humidity and Through Desalination." In *Le Dessalement des Materiaux Poreux 7es Jonrnees D'Etudes de La SFIIC Poitiers*, 9- 10 Mai 1996, p. 137-44. Champs-sur-Marne: SFIIC, 1996.



- Paterakis, Alice Boccia. "A Comparative Study of Soluble Salts in Contaminated Ceramics." In 8th Triemial Meeting: Sydney, Australia 6-11 September, 1987 Preprints, p. 1017-1021. Los Angeles: Getty Conservation Institute, 1987.
- Paterakis, Alice Boccia. "Efflorescence Testing on Pottery." In *The Ceramics Cultural Heritage Proceedings of the International Symposium on Ceramics in Architecture of the 8th CIMTEC-World Ceramics Congress and Forum on New Materials Florence, <i>Italy June 28-July 1, 1984*, edited by P. Vincenzini, p.661-668. Faenza: L Techna, 1995.
- Paterakis, Alice Boccia. "The Consolidation and Desalination of Ceramic Impregnated with Calcium Acetate." In 10th Triennial Meeting Washington D.C., USA 22-27 August 1993, Preprints, p. 704-708. Paris: ICOM, 1993.
- Paterakis, Alice Boccia. "A Preliminary Study of Salt Efflorescence in the Collection of the Ancient Agora, Athens, Greece." In 9th Triennial Meeting: Dresden, German Democratic Republic, 26-31 August, 1990: Preprints, p. 675-679. Los Angeles: 1COM Committee for Conservation. 1990.
- Pearson, Colin (ed.). *Conservation of Marine Archaeological Objects*. London: Buttersworth, 1987.
- Pessoa, J. Costa, J. L. Farinha Antunes, M. O. Figueiredo, and M. A. Fortes. "Removal and Analysis of Soluble Salts From Ancient Tiles." *Studies in Conservation*, Vol. 41 (1996): p. 153-160.
- Piacenti, F. "Terracotta Tiles- Evolution Phenomena Causing Aesthetic and Functional Anomalies: Origin, Prevention, Elimination." In *Ceramics in Architecture Proceedings of the International Symposium on Ceramics in Architecture of the 8th CIMTEC-World Ceramics Congress and Forum on New Materials Florence, Italy June 28-July 1, 1984*, edited by P. Vincenzini, p.581-588. Faenza:L Techna, 1995.
- Price, C. A. "Salt Damage in Monuments and Means of Control." In Science and Site: Evaluation and Conservation: the Archaeological Sciences Conference 1993; Proceedings of the Conference Held 8-10 September 1993 at Bournemonth University, edited by John Beavis, p. 229-237. Bourenmouth: Poole, 1995.
- Price, Clifford, and Peter Brimblecombe. "Preventing Salt Damage in Porous Materials." In *Preventive Conservation, Practice, Theory and Research: Preprints of the Contributions to the Ottawa Congress, 12-16 September 1994*, p. 90-93. London: International Institute for Conservation of Historic and Artistic Works, 1994.
- Price, Clifford. "Atmospheric Pollution and Stone Decay." *Conservation Bulletin* No.5, (June 1998) p. 4-5.

- Price, Clifford. "Stone-Decay and Preservation." In *Masomy Conservation and Cleaning Handbook*, edited by Keith Blades et al., p. 128-131. Ottawa: Association For Preservation Technology, 1985.
- Prudon, Theodore H. M. "Architectural Terra Cotta: Analyzing the Deterioration Problems & Restoration Approaches." *Technology and Conservation*, Vol. 3, Number 3. (Fall 1978), p. 30-38.
- Puehringer, J. and L Engström. "Unconventional Methods for the Prevention of Salt Damage." In *Vth International Congress on Deterioration and Conservation of Stone, Lansanne 25-27 September 1985*, edited by G. Félix, p. 241-249. Lausanne: Presses Polytechniques Romandes, 1985.
- Puehringer, J. and TH Perander. "Extraction of Salt from Materials of Coarse Porosity." In *Vth International Congress on Deterioration and Conservation of Stone*, *Lansanne 25-27 September 1985*, edited by G. Félix, p. 251-267. Lausanne: Presses Polytechniques Romandes, 1985.
- Puehringer, J., L. Berntsson, B. Hedberg. "Hydrate Salts and Degradation of Materials." In *Vth International Congress on Deterioration and Conservation of Stone*, *Lansanne 25-27 September 1985*, edited by G. Félix, p. 231-239. Lausanne: Presses Polytechniques Romandes, 1985.
- Pühringer, Josef, and Johannes Weber. "A Model for Salt Extraction Some Principles." In 9th Triemnial Meeting: Dresden, German Democratic Republic, 26-31 Angust, 1990: Preprints, p. 355-359. Los Angeles: ICOM, 1990.
- Pühringer, Josef, and Johannes Weber. "Salt Action and Materials Testing." In 9th Triemnial Meeting: Dresden, German Democratic Republic, 26-31 August, 1990: Preprints, p. 361-365. Los Angeles: ICOM, 1990.
- Pühringer, Joseph. "Deterioration of Materials by Hydraulic Pressure in Salt/Water Systems An Outline Model." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 545-556. Berlin: Moller Druck und Verlag, 1996.
- Pungor, Erno. A Practical Guide to Instrumental Analysis. Boca Raton: CRC Press, 1995.
- Rieger, Philip H. Electrochemistry. Englewood: Prentice-Hall Inc., 1987.
- Ritchie, T. "Efflorescence." In *Masonry Conservation and Cleaning Handbook*, edited by Keith Blades et al, p. 142-145. Ottawa: Association For Preservation Technology, 1985.

- Rossi-Manaresi, R., and A. Tucci. "Pore Structure and the Disruptive or Cementing Effect of Salt Crystallization in Various Types of Stone." *Studies in Conservation* Vol. 36 (1991): p. 53-58.
- Rudy, Maria. "Conservation of the Renaissance Tiles from the Grand Stove in Gdansk Artus Court." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1727-1736. Berlin: Moller Druck und Verlag, 1996.
- "Sawyer, Donald T., William R. Heineman, and Janice M. Beebe. *Chemistry Experiments for Instrumental Methods.* New York: John Wiley & Sons, 1984.
- Skibinski, S. "Efficiency of Salt Removal by Membrane Electrodialysis." In Wiener Berlichte Über Naturwissenschaft in Der Kunst Soppelband 2/3 1985/86, edited by Alfred Vendl et al, p. 260-271. Vienna: Hochschule Fur Angewandte Kunst, 1986.
- Skibinski, Slawomir. "Salt Removal from Stone Historical Objects by Means of Membrane Electrodialysis." In *17th International Congress on Deterioration and Conservation of Stone*, Lausanne 25-27 September 1985, edited by G. Félix, p. 959-965. Lausanne: Presses Polytechniques Romandes, 1985.
- Skibinski, Slawomir. "The Participation of Water-Soluble Salts in the Processes of Destruction of Historic Stone Artifacts and Conservation Techniques of Reducing their Effect." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 519-520. Brescia, Italy: Grafo, 1990.
- Skoog, Douglas A., Donald M. West, and F. James Holler. *Fundamentals of Analytical Chemistry Sixth Edition.* Fort Worth: Saunders College Publishing, 1963.
- Sloop, Jessica Amy. "Repair of Damaged Glazed Terra Cotta Surfaces: A Comparative Study of Remedial Coatings for Their Effectiveness on Areas of Glaze Loss in Temperate Maritime Weathering Conditions." Master of Science Thesis. Philadelphia: University of Pennsylvania, 1996.
- Smith, Donald E. and Fred H. Zimmerli. *Electrochemical Methods of Process Analysis*. Pittsburgh: Instrument Society of America, 1972.
- "Soluble Salts and Deterioration of Archeological Materials." *Conserve O Gram* Number 6/5 (August 1998).
- Somsiri, S., S. Zsembery, and J. A. Ferguson. "A Study of Pore Size Distributions in Fired Clay Bricks in Relation to Salt Attack Resistance." In *Proceedings of the 7th International Brick Conference Melbourne Australia 17-20 February 1985*, edited

- by Tom McNeilly and John C. Scrivener, p. 253-260. Melbourne: University of Melbourne, 1985.
- Steiger, Micahel, and Anke Zeunert. "Crystallization Properties of Salt Mixtures:

 Comparison of Experimental results and Model Calculations." In *Proceedings of the*8th International Congress on Deterioration and Conservation of Stone Berlin, 30

 September 4 October 1996, edited by Joseph Riederer, p. 535-545. Berlin: Moller Druck und Verlag, 1996.
- Strusholm, A. M. "Overglaze Polychrome Cone No. 6." *Journal of the American Ceramic Society* Vol. 14, (October 1931), p. 751-754.
- Technical Committee ECB/30 Cleaning and Surface Repair of Buildings. "Second Draft Amendment No.1 to be 6270: Code of Practice for Cleaning and Surface Repair of Buildings Part 1. Natural Stone, Cast Stone and Clay and Calcium Silicate Brick Masonry." London: British Standards Institute, 1982.
- Torraca, G. Porons Building Materials. Rome: ICCROM, 1982.
- Tunick, Susan. "The Reign of Terra Cotta in the United States: Enduring in an Inhospitable Environment, 1930-1968. *APT Bulletin* Vol. 29 No. 1 (1998): p. 43-48.
- Venkataraman, Anuradha. "The Conservation of Salt-Contaminated Stone." Master of Science Thesis. Philadelphia: University of Pennsylvania, 1992.
- Viles, H. A., and C. A. Moses. "SEM Based Studies of the Combined Effects of Salt and Biological Weathering on Calcareous Building Stones." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 557-561. Berlin: Moller Druck und Verlag, 1996.
- Vitina, Inta, Silvija Igaune, Linda Krage, and Ojars Baumanis. "Problems of Soluble Salts in the Monuments of Latvia." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 477-479. Berlin: Moller Druck und Verlag, 1996.
- Wallasch, S., F. Schlutter, H. Juling, and R. Blaschke. "Weathering and Conservation of North German Terracotta Schwerin Castle as a Case Study." In *Conservation of Historic Brick Structures Case Studies and Reports of Research*, edited by N. S. Baer, S. Fitz, and R. A. Livingston, p. 347-359. London: Donhead Publishing Ltd., 1998.
- Weast, Robert C. (ed.). *CRC Handbook of Chemistry and Physics* 58th Edition. Cleveland: CRC Press, 1978.

- Weber, Helmut. *Mauerfenchtigkeit: Ursachen und Gegenmaßnahmen.* 2nd Ed., Sindelfingen, Germany: Expert Verlag 1984.
- Wessman, Lubica. "Studies of Salt-Frost Attack on Natural Stone." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 563-571. Berlin: Moller Druck und Verlag, 1996.
- Wheeler, George Segan and Mark T. Wypyski. "An Unusual Efflorescence on Greek Ceramics." *Studies in Conservation* Vol. 38 (1993): p. 55-62.
- Winkler, E. M. "Decay of Stone." In *Preprints of the Contributions to the New York Conference on Conservation of Stone and Wooden Objects, 7-13 June 1970 Vol. 1*, p. 1-14. London: International -Institute for Conservation of Historic and Artistic Works, 1971.
- Winkler, Erhard M. "The Decay of Building Stones: A Literature Review." In *Masonry Conservation and Cleaning Handbook*, edited by Keith Blades et al, p. 132-141. Ottawa: Association For Preservation Technology, 1985.
- Wittenburg, C., E. Wendler, and M. Steiger. "Terracotta at Schloß Schwerin, Different Desalination Treatments for the Application of Stone Consolidating Agents." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1717-1726. Berlin: Moller Druck und Verlag, 1996.
- Wittenburg, Christian and Walter Dannecker. "Salt Enrichment in Building Stones by Deposition of Sulfur and Nitrogen Containing Species from Urban Atmospheres." In *Stone and Monuments: Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994*, edited by Vasco Fassina et al., p. 179-183. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Yeager, Ernest and Alvin J. Salkind. *Techniques of Electrochemistry Volume 2.* New York: John Wiley & Sons, 1973.
- Zappia, Giuseppe, C. Sabbioni, and G. Gobbi. "Weathering Layers on Stone Monuments in Maritime Localities of Northern and Central Italy." In *The Conservation of Monuments in the Mediterranean Basin The Influence of Coastal Environment and Salt Spray on Limestone and Marble Proceedings of the 1st International Symposium Bari 7-10 June 1989*, edited by Fulvio Zezza, p. 79-82. Brescia, Italy: Grafo, 1990.
- Zehnder, K. "New Aspects of Decay Caused by Crystallization of Gypsum." In Conservation of Stone and Other Materials Volume One Causes of Disorders and Diagnosis Proceedings of the International RILEM UNESCO Congress Paris June 29 July 1, 1993, edited by M. J. Thiel, p. 107-114. London: E & FN Spon, 1993.

- Zehnder, K. and A. Arnold. "Stone Damage Due to Formate Salts." *Studies in Conservation*, Vol. 29 (1984): p. 32-34.
- Zehnder, Konrad. "Gypsum Efflorescence in the Zone of Rising Damp Monitoring of Slow Decay Processes caused by Crystallizing Salts on Wall Paintings." In *Proceedings of the 8th International Congress on Deterioration and Conservation of Stone Berlin, 30 September 4 October 1996*, edited by Joseph Riederer, p. 1669-1685. Berlin: Moller Druck und Verlag, 1996.
- Zezza, Fulvio. "Marine Spray and Polluted Atmosphere as Factors of Damage to Monuments in the Mediterranean Coastal Environment." In *Stone and Monuments:* Methodologies for the Analysis of Weathering and Conservation Proceedings of the 3rd International Symposium Venice 22-25 June 1994, edited by Vasco Fassina et al. p. 269-273. Venice: Soprintendenza ai Beni Artistici e Storici di Venezia, 1994.
- Zimmt, Werner S. and Nancy Odegaard. "Conductivity Measurements: A Discussion and Comparison of Two Instruments Used to Follow the Removal Soluble Salts from Ceramics." *WAAC Newsletter* Vol. 5, No. 3 (Sept. 193); p. 25-28.



INDEX

Atmospheric Pollution, 11, 15 Berlin, 21 Brick, 6, 11, 12, 17, 20 Capillary Condensation, 6, 7 Capillary Rise, 7, 9, 15, 16 Chemical Barriers, 16 Chemical Disintegration, 6 Colonial Williamsburg, 12, 15, 20 Consolidants, 7 Cuneiform Tablets, 24 Deicing Salts, 10 Efflorescence, 1, 8, 9, 13, 17, 18 Freeze-Thaw, 7 Hygroscopic, 7, 9 Impermeable Barrier, 15 Metallic Salts, 11 Nondestructive Testing, 15, 80

Quartz, 27, 30, 33

Portland Cement, 12



Subflorescence, 8, 17

Venice, 20

Water repellent, 7, 16

Water Vapor Transmission, 7, 17





Anne & Jerome Fisher FINE ARTS LIBRARY

University of Pennsylvania

Please return this book as soon as you have finished with it. It must be returned by the latest date stamped below.



FISHER FINE ARTS LIZEPARY

APR 3 2000

UNIV. OF PENNA.

N/1198/02651/7354X

n. Le

